3. PARK AVENUE

4000500	TAVID	DATE OF CONCERNATION	OLONIETO ANIOE	
ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:	
15 Park Avenue	069.13-1-3	Ca. 1880s	N – Significantly altered; does	
			not contribute to potential NR	
			district	
CONDITION:		NAME:		
Fair		DECORPTION		
		DESCRIPTION:		
		2-story cross-gable frame	vernacular house: brick	
	NID.	foundation, fiberboard sid		
		Includes two separate cor		
			at the main house and an entry	
			width entry porch. Windows are	
			units with some 6/1 wood sash	
			atures tripartite wood casement	
		window, irregular, altered fenestration. Small 1-story shed roof addition at north side.		
		Tool addition at north side.		
		USN 05541.000439		
		0311 03341.000439		
ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:	
16 Park Avenue	069.53-1-9	Ca. 1860s	D – Contributes to potential NR	
			district	
CONDITION:		NAME:		
Good				
		DESCRIPTION:		
		1 1/-story side-gable fram	o vernacular house: sandstone	
A STATE VIEW TO		1 ½-story side-gable frame vernacular house; sandstone foundation; synthetic wood siding, asphalt shingle roof.		
		Full width open entry porch with square chamfered wood		
		columns and wood balustrades. Windows typically 1/1		
			replacement units. 1-story mass at rear of building.	
		Property includes non-contributing small shed.		
		LICN 05544 000277		
The state of the s		USN 05541.000277		

ADDRESS: 19 Park Avenue	TAX ID: 069.13-1-4	DATE OF CONSTRUCTION: Ca. 1860	SIGNIFICANCE: D – Contributes to potential NR district
CONDITION: Good		NAME: Benjamin Maxon House DESCRIPTION:	
		2 ½-story front-gable frame vernacular house with modest Italianate porch; concrete block foundation, vinyl siding, asphalt shingle roof. Single-bay open entry porch with square wood columns and balustrades, wooden brackets at cornice, wood paneled entry door. Windows typically 1/1 wood sash double hung units. Gable end features single window. North side includes single bay entry addition, south side features recessed single bay entry. Property includes contributing 1 ½-story side-gable wooden barn complete with sliding barn door.	
ADDRESS: 20 Park Avenue	TAX ID: 069.53-1-10	DATE OF CONSTRUCTION: Ca. 1900	SIGNIFICANCE: N – Significantly altered; does not contribute to potential NR district
CONDITION: Good		NAME:	
		DESCRIPTION:	
		2-story front-gable frame vernacular house; Medina sandstone foundation, wood clapboard siding, asphalt shingle roof. Full width partially enclosed entry porch, contemporary entry door and bay windows. 1/1 replacement window units typical throughout with irregular fenestration. Gable end features various types of wood shingles. South side features a 1 st story bay window and north side includes an enclosed staircase leading to the second story.	
ADDRESS: 23 Park Avenue	TAX ID: 069.13-1-5	DATE OF CONSTRUCTION: Ca. 1880s	SIGNIFICANCE: D – Contributes to potential NR district
CONDITION: Good		NAME:	
		DESCRIPTION:	
		siding, asphalt shingle roc with spindlework supports brackets, historic double v typically 1/1 replacement of Two story bay window with	ng; parged foundation, vinyl of. Half width open entry porch and balustrades, decorative wooden entry door. Windows units with irregular fenestration. ch corner brackets, decorative adow with large central lite

24 Park Avenue 069.53-1-11 1908 D - Contributes to potential NR district CONDITION: Good DESCRIPTION: 2 ½-story cross-gable frame house with modest Queen Anne styling; concrete block foundation, wood clapboard siding, asphalt shingle roof. Full width enclosed entry porch with contemporary door. Windows typically 1/1 wood sash double hung, some with leaded glass upper sashes, bay window at second story. Gable end features wooden fish scale shingle siding, wooden window with semicircular transoms. Single front-gable dormer with fish scale shingles. USN 05541.000280 ADDRESS: TAX ID: OATE OF CONSTRUCTION: Ca. 1870s D - Contributes to potential NR district; Designated local landmark CONDITION: MAME: Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building. USN 05541.000281	ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
CONDITION: Good DESCRIPTION: 2 ½-story cross-gable frame house with modest Queen Anne styling; concrete block foundation, wood clapboard siding, asphalt shingle roof. Full width enclosed entry porch with contemporary door. Windows typically 1/1 wood sash double hung, some with leaded glass upper sashes, bay window at second story. Gable end features wooden fish scale shingle siding, wooden window with semicircular transoms. Single front-gable dormer with fish scale shingles. USN 05541.000280 ADDRESS: 41 Park Avenue TAX ID: 069.13-2-1 DATE OF CONSTRUCTION: Ca. 1870s SIGNIFICANCE: D - Contributes to potential NR district; Designated local landmark NAME: Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quarrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.				
DESCRIPTION: 2 ½-story cross-gable frame house with modest Queen Anne styling; concrete block foundation, wood clapboard siding, asphalt shingle roof. Full width enclosed entry porch with contemporary door. Windows typically 1/1 wood sash double hung, some with leaded glass upper sashes, bay window at second story. Gable end features wooden fish scale shingle siding, wooden window with semicircular transoms. Single front-gable dormer with fish scale shingles. USN 05541.000280 DATE OF CONSTRUCTION: Ca. 1870s DATE OF CONSTRUCTION: Ca. 1870s D- Contributes to potential NR district; Designated local landmark Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quarrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.				•
DESCRIPTION: 2 ½-story cross-gable frame house with modest Queen Anne styling; concrete block foundation, wood clapboard siding, asphalt shingle roof. Full width enclosed entry porch with contemporary door. Windows typically 1/1 wood sash double hung, some with leaded glass upper sashes, bay window at second story. Gable end features wooden fish scale shingle siding, wooden window with semicircular transoms. Single front-gable dormer with fish scale shingles. USN 05541.000280 ADDRESS: 41 Park Avenue TAX ID: 069.13-2-1 DATE OF CONSTRUCTION: Ca. 1870s D - Contributes to potential NR district; Designated local landmark CONDITION: Good NAME: Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.			NAME:	
2 ½-story cross-gable frame house with modest Queen Anne styling; concrete block foundation, wood clapboard siding, asphalt shingle roof. Full width enclosed entry porch with contemporary door. Windows typically 1/1 wood sash double hung, some with leaded glass upper sashes, bay window at second story. Gable end features wooden fish scale shingle siding, wooden window with semicircular transoms. Single front-gable dormer with fish scale shingles. USN 05541.000280 ADDRESS: 41 Park Avenue TAX ID: 069.13-2-1 DATE OF CONSTRUCTION: Ca. 1870s DATE OF CONSTRUCTION: Ca. 1870s SIGNIFICANCE: D – Contributes to potential NR district; Designated local landmark NAME: Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.	Good		DESCRIPTION	
Anne styling; concrete block foundation, wood clapboard siding, asphalt shingle roof. Full width enclosed entry porch with contemporary door. Windows typically 1/1 wood sash double hung, some with leaded glass upper sashes, bay window at second story. Gable end features wooden fish scale shingle siding, wooden window with semicircular transoms. Single front-gable dormer with fish scale shingles. USN 05541.000280 ADDRESS: 41 Park Avenue TAX ID: 069.13-2-1 DATE OF CONSTRUCTION: Ca. 1870s D - Contributes to potential NR district; Designated local landmark Myron O. Randall House DESCRIPTION: 2 '2y-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.			DESCRIPTION:	
41 Park Avenue O69.13-2-1 Ca. 1870s D — Contributes to potential NR district; Designated local landmark CONDITION: Good NAME: Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.			Anne styling; concrete block foundation, wood clapboard siding, asphalt shingle roof. Full width enclosed entry porch with contemporary door. Windows typically 1/1 wood sash double hung, some with leaded glass upper sashes, bay window at second story. Gable end features wooden fish scale shingle siding, wooden window with semicircular transoms. Single front-gable dormer with fish scale shingles.	
CONDITION: Good NAME: Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.	ADDRESS:		DATE OF CONSTRUCTION:	0.0
CONDITION: Good NAME: Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.	41 Park Avenue	069.13-2-1	Ca. 1870s	•
CONDITION: Good NAME: Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.				
Myron O. Randall House DESCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.	CONDITION:		NAME:	landmark
DÉSCRIPTION: 2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.			· · · · · · · · · · · · · · · · · · ·	
styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.	0000			
			2 ½-story cross-gable frame house with Gothic Revival styling; fieldstone foundation, wood clapboard siding, asphalt shingle roof. Wrap around open entry porch with round columns and metal balustrades, historic recessed double entry door. Windows typically 1/1 wood sash double hung with some historic wooden storm windows intact, decorative wooden frames and bracketed hoodmolds. Bracketed cornice, gable end features wooden quatrefoil window and decorative wooden vergeboard. Two story bay window and secondary porch at north side. Attached 2-bay garage at rear of building.	

ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
47 Park Avenue	069.13-2-24	Ca. 1880s	D – Contributes to potential NR
			district
CONDITION:	CONDITION:		
Excellent			
Excellent		DESCRIPTION: 2 ½-story cross-gable frame house with Eastlake styling; sandstone foundation, wood clapboard siding, asphalt shingle roof. Features nearly full width open entry porch with square wooden supports and balustrade, wood paneled entry door complete with multi-lite transom and sidelite door surround. Recessed shed roof addition with 8-lite casement windows. Other windows typically 1/1 wood sash double hung with some leaded glass upper sashes, decorative wooden windows frames with flat bracketed hood molds. Gable end includes paired wooden double hung windows, upper sashes feature large central lite surrounded by smaller lites. Property includes contributing hipped roof 2-bay garage.	
ADDRESS:	TAX ID:	USN 05541.000282 DATE OF CONSTRUCTION: SIGNIFICANCE:	
50 Park Avenue	069.53-2-9	Ca. 1920s	D – Contributes to potential NR district
CONDITION:		NAME:	
Good		DESCRIPTION	
		DESCRIPTION: 1 ½-story front-gable frame vernacular building; parged foundation aluminum siding, asphalt shingle roof. Half width enclosed entry porch. Windows typically 1/1 replacement, paired at first story, single at gable end. Property includes non-contributing contemporary gambrel roof shed. USN 05541.000442	

ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
51 Park Avenue	069.13-2-23	Ca. 1855	D – Contributes to potential NR district
CONDITION:		NAME:	
Excellent		Helen Lyford House DESCRIPTION:	
		2 ½-story cross-gable frame house with modest Greek Revival styling; stone foundation, wood clapboard siding, asphalt shingle roof. Full width open entry porch with round columns and wooden balustrades, historic wooden double entry door. Windows typically 6/6 simulated divided light vinyl replacements topped with decorative wooden triangular pediments. Gable end features single window covered with wooden shutter. Property includes contributing front gable single-bay garage. USN 05541.000283	
ADDRESS: 54 Park Avenue	TAX ID: 069.53-2-10	DATE OF CONSTRUCTION: Ca. 1960s	SIGNIFICANCE: D – Contributes to potential NR district; Designated local landmark
CONDITION: Excellent		NAME:	
		DESCRIPTION:	
		2-story cross-gable with mansard frame house with modest Queen Anne styling; parged sandstone foundation, wood clapboard siding, asphalt shingle roof. Full width open entry porch with spindlework supports and wooden balustrade. Windows typically 1/1 replacement units with some wooden storm windows, irregular fenestration. Gable end features wooden fish scale shingles.	
		USN 05541.000443	
ADDRESS: 55 Park Avenue	TAX ID: 069.13-2-22	Ca. 1910	SIGNIFICANCE: D – Contributes to potential NR district
CONDITION: Good		NAME:	
		DESCRIPTION:	
		concrete block foundation roof. Full width open entry columns and balustrades, single lite. Windows typica with irregular fenestration, end features pent roof and	ne vernacular house; rock faced, vinyl siding, asphalt shingle porch with round wooden wooden entry door with large ally 1/1 wood sash double hung bay window at 1 st story. Gable disingle window. Property contemporary gambrel roof

ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
58 Park Avenue	069.53-2-11	Ca. 1860s	D – Contributes to potential NR
			district
CONDITION: Good		NAME:	
		DESCRIPTION:	
		2-story cross-gable frame vernacular house; parged foundation, asbestos siding, asphalt shingle roof. 2-bay recessed open entry porch with square supports and metal balustrade, wooden entry door with large single light and single sidelite. 1/1 wood windows with vinyl shutters typical throughout, irregular fenestration. Tripartite replacement window at first story with stone veneer underneath. Cutaway bay at corner. Property includes contributing 2 ½-story front-gable wooden barn with contemporary metal garage door. USN 05541.000444	
ADDRESS: 63 Park Avenue	TAX ID: 069.13-2-21	DATE OF CONSTRUCTION: Ca 1840s	SIGNIFICANCE: D – Contributes to potential NR district; Designated local landmark
CONDITION:		NAME:	
Excellent		Rogers-Selden House DESCRIPTION:	
		2-story hipped roof painted brick house with Italianate styling; fieldstone foundation, asphalt shingle roof. Single bay open entry porch with wood supports and decorative brackets, side rear porch matches front porch decorative details. Windows typically 1/1 wood sash double hung with wooden shutters and prominent stone lintels. Roof features iron cresting. Attached garage at rear. Property includes contributing 2-story front-gable wooden barn.	
		USN 05541.000014	
ADDRESS: 67 Park Avenue	TAX ID: 069.13-2-20	DATE OF CONSTRUCTION: Ca.1870s	SIGNIFICANCE: D – Contributes to potential NR district
CONDITION: Fair		NAME:	
raii		DESCRIPTION:	
		2-story cross-gable frame foundation, vinyl siding, as wrap around open entry proclumns and balustrades, wooden entry doors. Wind double hung, two story ba	recessed historic double dows typically 1/1 wood sash y window at south side ear porch. Property includes

ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
73 Park Avenue	069.13-2-19	1833	D – Contributes to potential NR
			district; Designated local landmark
CONDITION:		NAME:	lariaman
Excellent		Durand-Hewett House	
		DESCRIPTION:	
		2 ½-story front-gable frame house with Italianate styling; parged foundation; vinyl siding, asphalt shingle roof. Single bay open entry porch with decorative square wooden supports and brackets, historic wooden double entry door. North side features secondary entry porch with decorative wooden supports and brackets similar to front porch, includes wooden balustrades. Windows typically 6/6 wood sash double hung with vinyl shutters and bracketed flat hood molds, irregular fenestration. Large brackets at cornice, wooden porthole window and cornice returns at gable end. Property includes contributing 2 ½-story wooden barn/garage.	
ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
74 Park Avenue	069.53-3-10	1856	D – Contributes to potential NR district
CONDITION:		NAME:	
Good		DESCRIPTION:	
		2-story front-gable frame vernacular house; field stone foundation, asbestos siding, asphalt shingle roof. Single-bay open entry porch with spindlework supports, contemporary entry door, matching secondary porch and 1-story addition at south side elevation. Windows typically 1/1 wood sash double hung with triangular pediments, some wooden storm windows throughout. Property includes contributing 2-story wooden barn.	
The state of the state of the state of the		USN 05541.000285	

ADDRESS: 79 Park Avenue	TAX ID: 069.13-2-18	DATE OF CONSTRUCTION: Ca. 1860s	SIGNIFICANCE: D – Contributes to potential NR district; Designated local landmark
CONDITION: Excellent		NAME: Enos Chappell House	
		DESCRIPTION: 2-story cross-gable brick house with Italianate styling; stone foundation, asphalt shingle roof. Single bay recessed open entry porch with decorative bracketed wood supports, historic double wooden door with transom above. Windows typically 1/1 wood sash double hung with semicircular stone arch hood molds and stone sills. Large 1-story rear porch addition with Doric columns. Property includes non-contributing single-bay wooden garage with decorative vergeboard. USN 05541.000286	
ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
80 Park Avenue	069.53-3-11	Ca. 1860s	D – Contributes to potential NR district
CONDITION: Good		NAME:	
		2-story cross-gable frame house with modest Greek Revival styling; vinyl and stone veneer siding, asphalt shingle roof. Small open entry porch with wood supports and balustrade, side-facing entry door. Windows typically 6/6 wood sash double hung with irregular fenestration, 1 st story windows grouped. Second story features small 3-light casement windows. Property includes contributing 2-story front-gable wooden barn. USN 05541.000287	
ADDRESS: 86 Park Avenue	TAX ID: 069.53-3-12	DATE OF CONSTRUCTION: Ca. 1860s	SIGNIFICANCE: D – Contributes to potential NR
CONDITION:		NAME:	district
Good		DESCRIPTION:	
		2 ½-story hipped roof fram Medina sandstone founda shingle roof. Full width op square wooden supports, recessed side entry porch details. Historic double we lites. Windows typically 1/ flat hoodmolds, irregular fo	ne house with Italianate styling; ition, asbestos siding, asphalt ben entry porch with decorative and spindlework balustrade, features same decorative coden entry door with multiple 1 wood sash double hung with enestration. Square cupola at contributing 2 ½-story hipped roof

ADDRECC.	TAV ID:	DATE OF CONCEDUCTION	CICNIFICANCE.
ADDRESS: 87 Park Avenue	TAX ID: 069.13-4-1	DATE OF CONSTRUCTION: Ca. 1860s	SIGNIFICANCE: D – Contributes to potential NR
or Faik Aveilue	009.13-4-1	Ca. 10005	district; Designated local
			landmark
CONDITION:		NAME:	ianumark
Excellent		Bushnell House	
ZXONON		DESCRIPTION:	
		2 ½-story cross-gable frame vernacular house with Craftsman style porch; sandstone foundation, wood clapboard siding, asphalt shingle roof. Nearly full width open entry porch with grouped battered wood columns and solid rusticated shingle sided balustrade. Windows typically 1/1 wood sash double hung with flat hoodmolds. 1 st story features bay window at north side elevation. Gable end includes single pointed arch window covered window with wood shutter. Properly includes contributing hipped roof wooden garage with flared eaves. USN 05541.000289	
ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
91 Park Avenue	069.13-4-30	Ca 1880s	D – Contributes to potential NR
			district; Designated local landmark
CONDITION:		NAME:	ianumaik
Fair		Horace Collins House	
		DESCRIPTION:	
		Queen Anne styling; sand clapboard siding, asphalts around open entry porch vibalustrade and pediment a wood entry doors. Window double hung with some wo	shingle roof. Full width wrap

ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
92 Park Avenue	069.53-3-13	Ca 1850s	D – Contributes to potential NR
			district; Designated local
			landmark
CONDITION:		NAME:	
Good			
		DESCRIPTION:	
		1 ½-story front-gable painted brick houses with modest Greek Revival styling; stone foundation asphalt shingle roof. Single-bay open entry porch with square columns and pediment. Windows typically 1/1 wood sash double hung with wood shutters, irregular fenestration. South side features 1-story fully enclosed wood porch addition. Property includes non-contributing contemporary 3-bay front gable garage. USN 05541.000290	
ADDRESS:	TAX ID:	DATE OF CONSTRUCTION: SIGNIFICANCE:	
96 Park Avenue	069.53-3-14	Ca. 1905	D – Contributes to potential NR
			district
CONDITION:		NAME:	
Good			
		DESCRIPTION:	
		1 ½-story cross-gable frame vernacular building with modest Craftsman styling; concrete block foundation, vinyl siding, asphalt shingle roof. Full width open entry porch with square vinyl sided supports and vinyl sided solid balustrade, two separate wood paneled entry doors. Windows typically 1/1 wood sash double hung with some leaded glass upper sashes. Tripartite window and cornice returns at gable end. Bay windows at north and south side elevations.	
		USN 05541.000456	

ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
101 Park Avenue	069.13-4-29	1864	D – Contributes to potential NR
To Trank / Worldo	000.10 1 20	1001	district; Designated local
			landmark
CONDITION:		NAME:	Tario Train
Excellent		Josiah Randolph House	
		DESCRIPTION:	
		2-story front-gable and wing frame house with Greek Revival styling; sandstone foundation, wood shingle siding, asphalt shingle roof. Single bay open entry porch with square wood supports, metal balustrades and pediment, wooden entry door. 3-bay secondary entry porch square wood supports and metal balustrades. Windows typically 6/6 wood sash double hung with wooden storm windows. Cornice returns at gable end and roof of wing features front gable dormer with paired windows. Property includes contributing 2 ½-story front-gable barn.	
ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
107 Park Avenue	069.13-4-28	Ca. 1830s	D – Contributes to potential NR
			district; Designated local
			landmark
CONDITION:		NAME:	
Excellent		A. D. Cook House	
		DESCRIPTION:	
		2-story front-gable and wing painted brick house with Greek Revival styling; sandstone foundation, asphalt shingle roof. Entry door flanked by pilasters. 3-bay secondary entry porch square wood supports and metal balustrades. Windows typically 1/1 wood sash double hung. Cornice returns at gable end and roof of wing features shed dormer. Attached single-bay garage at rear.	
Contract of the same of		USN 05541.000291	

ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
110 Park Avenue	068.68-2-7	Ca. 1910	N – Significantly altered; does
1101 dik / Worldo	000.00 2 7	Ga. 1010	not contribute to potential NR
			district
CONDITION:		NAME:	
Fair			
		DESCRIPTION:	
		1 ½-story cross-gable frame vernacular house; asbestos siding, asphalt shingle roof. Nearly half width enclosed recessed entry porch with contemporary entry door. Windows typically 1/1 wood sash double hung with shutters. Projecting 1-story window bay at front-gable portion. Includes attached 2-story wooden front-gable barn.	
		USN 05541.000453	
ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
121 Park Avenue	069.13-5-25	Ca 1860s	D – Contributes to potential NR
CONDITION:		district	
Good			
		DESCRIPTION:	
		1 ½-story cross-gable frame vernacular house with modest Greek Revival styling; fieldstone foundation, wood shingle siding, asphalt shingle roof. Features half width fully enclosed entry porch, secondary entry at north side elevation. Windows typically 1/1 wood sash double hung with irregular fenestration, second story features small single-lite wood casement windows. Includes single-bay attached garage.	
		USN 05541.000189	
ADDRESS:	TAX ID:	DATE OF CONSTRUCTION:	SIGNIFICANCE:
Park Avenue CONDITION:	069.13-5-28	Ca. 1870s NAME:	I – Potentially individually NRE
Fair		Former Apple Warehouse	
		DESCRIPTION:	
		1-story hipped roof frame foundation, wood clapboal roof. Several wood panel elevation, windows typical	vernacular freight house; parged rd siding, standing seam metal entry doors on north side ly boarded up. Exposed eaves sed brick parapet bisects the