Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	14 Academy Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 113-west	1½ -story, side- gabled, Craftsman bungalow with gabled ½ porch, brick first story.	S
		41/ plant blant	
	18 Academy Street  Date: ca. 1920 Condition: Excellent Alterations:	1½ -story, hipped- roof, Craftsman bungalow with gabled ½ width porch, rock-faced concrete block foundation and brick first story.	S
	TAX MAP: 113-west		
	21 Academy Street  Date: ca. 1860 Condition: Good Alterations: Porch  TAX MAP: 109	2-story, L-shaped, Italianate house with porch at intersection, roof brackets, and paired windows.	S
	22 Academy Street  Date: ca. 1920 Condition: Excellent Alterations:	1½ -story, front- gabled, Craftsman bungalow with full- width porch.	С
	TAX MAP: 113-west		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	23 Academy Street  Date: ca. 1860 Condition: Good Alterations:	2-story, front-gabled, block with rear 2- story, hipped roof addition and wrap- around porch.	C
	TAX MAP: <b>109</b>		
	24 Academy Street  Date: ca. 1870 Condition: Good Alterations: Windows, Side entry porch, Rear extension	1 ½-story, front- gabled, extended vernacular house with side entrance.	NC
	TAX MAP: 113-west		
	43 Academy Street  Date: ca. 1860 Condition: Good Alterations: Attached garage, Entry porch  TAX MAP: 109	2-story, low-pitched hipped roof, Italianate house with 3-by 2-bays, entry porch.	С
	51 Academy Street  Date: ca. 1860 Condition: Good Alterations: Some windows, Open porch.	2-story, L-shaped, vernacular house with 2/2 windows and clapboard siding.	С
	TAX MAP: <b>109</b>		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	151 Academy Street  Date: ca. 1920 Condition: Good Alterations:	1½ -story, front- gabled, cottage shed dormers and front porch.	С
	TAX MAP: <b>110</b>		
	8 Backman Street  Date: ca. 1920 Condition: Good Alterations:	1½ -story front- gabled, Craftsman house with gabled side wall dormer, porch and clapboard siding.	S
	TAX MAP: 113-west		
	9 Backman Street  Date: ca. 1920 Condition: Good Alterations:	1½ -story, front- gabled, cottage with shed wall dormer, full-width porch and clapboard siding.	S
	TAX MAP: 113-west		
	10 Backman Street  Date: ca. 1920 Condition: Good Alterations:	1½ -story, front- gabled, Craftsman house with gabled side wall dormer, enclosed front porch, asbestos and wood shingles.	С
	TAX MAP: 113-west		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
n/a	14 Backman Street  Date: ca. 1920 Condition: Good Alterations:	2-story, hipped-roof, Craftsman house with wood shingles and addition	.C
	TAX MAP: 113-west		
	15 Backman Street  Date: ca. 1920 Condition: Good Alterations:	1½ -story, front- gabled, Craftsman bungalow with brick and wood shingle siding, and brick front porch, gabled dormer.	С
	TAX MAP: 113-west		
Figure 1 Language 1 La	19 Backman Street  Date: ca. 1920 Condition: Good Alterations: Porch enclosure. Masonry exterior painted	2-story, hipped-roof, Colonial Revival American Four- square with front hipped roof dormer and rock-faced concrete block walls.	С
	TAX MAP: 113-west		
	20 Backman Street  Date: 1890 Condition: Good Alterations:	2-story, front-gabled, vernacular house with full-width porch.	С
	TAX MAP: 113-west		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	26 Backman Street  Date: 1890 Condition: Good Alterations:	2½ -story, front- gabled, vernacular house with partial wrap-around porch.	C
	TAX MAP: 113-west		
	32 Backman Street  Date: ca. 1920 Condition: Excellent Alterations:	1½ -story, side- gabled, concrete block Colonial Revival with shed wall dormers and front porch.	S
	TAX MAP: 113-west		
	34 Backman Street  Date: ca. 1850 Condition: Excellent Alterations: Wing	1½ -story, front-gable and wing Greek Revival house with front porch on main block.	С
	TAX MAP: 113-west		
	40 Backman Street  Date: ca. 1920 Condition: Excellent Alterations:	1½ -story, side- gabled, Craftsman bungalow with gabled dormer and full-width porch.	S
	TAX MAP: 114-west		

44 Backman Street  Date: ca. 1920	1½ -story, side- gabled Craftsman bungalow with shed	S,C,NC
Condition: Excellent Alterations:	dormer and full-width porch.	
TAX MAP: 114-west		
51 Backman Street  Date: mid-19 <sup>th</sup> c.  Condition: Good  Alterations: Porch	2-story, front-gabled, vernacular house with full-width porch, clapboard siding.	С
TAX MAP: 114-west		
31 Bank Street  Date: ca. 1930 Condition: Good Alterations:	1-story, side-gabled bungalow with side wing and front screened porch.	С
	2½ -story front-	С
Date: ca. 1910 Condition: Good Alterations:	gabled, Colonial Revival house with rusticated concrete block walls and an open, full-width porch. "Kit" house.	3
	51 Backman Street  Date: mid-19 <sup>th</sup> c. Condition: Good Alterations: Porch  TAX MAP: 114-west  31 Bank Street  Date: ca. 1930 Condition: Good Alterations:  TAX MAP: 109  32 Bank Street  Date: ca. 1910 Condition: Good	51 Backman Street  Date: mid-19 <sup>th</sup> c. Condition: Good Alterations: Porch  TAX MAP: 114-west  31 Bank Street  Date: ca. 1930 Condition: Good Alterations:  TAX MAP: 109  32 Bank Street  Date: ca. 1910 Condition: Good Alterations:  Date: ca. 1910 Condition: Good Alterations:

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	35 Bank Street  Date: ca. 1870 Condition: Good Alterations:	2-story, L-shaped, front-gabled, vernacular house with covered entry at intersection and clapboard siding.	C
	10 Billsboro Street  Date: ca. 1920 Condition1: Good Alterations:	1-story, front-gabled, Craftsman bungalow with brick and concrete block construction, side wing and front porch.	С
	TAX MAP: 114-east		
	14 Billsboro Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 114-east	2-story, hipped-roof, Craftsman "kit" house with front and side gable wall dormers, front porch, rock faced concrete block on the first story and clapboard siding above.	S
	TAX WAI . 114-cast		
	16 Bird Road  Date: ca. 1860 Condition: Good Alterations:	2-story, L-shaped, brick, vernacular house with stone lintels and sills, porch at intersection.	С
	IVIAF FRAIVIE. <b>A4</b>		

Photo	Address/Date/Condition/ Alterations	Description	Rating
	9 Bliss Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 114-west	1½ -story, front- gabled, Craftsman bungalow with enclosed ¾ width front porch and wood shingles.	S,C,NC
	20 Bliss Street  Date: ca. 1850 Condition: Excellent Alterations:  TAX MAP: 117	2-story, front-gabled, vernacular house with side wing at rear. (Previously inventoried no determination.)	S
	89 Bliss Street  Date: ca.1890 Condition: Good Alterations:  TAX MAP: 114-east	2 ½-story T-shaped, Queen Anne house with enclosed porch and wood shingles.	С
	129 Bliss Street  Date: ca. 1820s / 1850 Condition: Good Alterations: Main block appears to have been originally constructed in the Federal style and later updated in the Italianate style.  TAX MAP: 115	2-story, side-gabled, Italianate house with 2-story front gabled rear wing. It has interior end chimneys, round arched windows.	S

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	177 Bliss Street  Date: ca.1830 Condition: Good Alterations: Addition with asbestos siding	1½ -story, brick, front gable with side wing Greek Revival with stone lintels and sills.	S
	TAX MAP: <b>115</b>		
	4 Brewer Place  Date: ca. 1940 Condition: Excellent Alterations:	2½ -story, cross- gabled,Colonial Revival house with a brick veneer and an enclosed entry porch, 1-story rear wing.	S
	TAX MAP: 113-west		
	14 Brewer Place  Date: ca. 1925 Condition: Excellent Alterations:  TAX MAP: 113-west	1½ -story, sidegabled, Craftsman house with ¾ width front porch, shed dormer, and wood shingles.	S
	15 Brewer Place	1½-story, side-	С
	Date: ca. 1948 Condition: Excellent Alterations:	gabled, Neo-Colonial house with stone façade, sidelights, 2-gabled dormers.	
	TAX MAP: 113-west		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	16 Brewer Place  Date: ca. 1925 Condition: Excellent Alterations: Rear addition  TAX MAP: 113-west	2-story, side-gabled, Craftsman house with open, full-width porch and wood shingles.	S
	17 Brewer Place  Date: ca. 1925 Condition: Excellent Alterations:  TAX MAP: 113-west	2½ -story, front- gabled block with lower asymmetrical 1 ½- story front-gabled wing, Craftsman style with cutaway corner entry porch.	S
	21 Brewer Place  Date: ca. 1925 Condition: Excellent Alterations:  TAX MAP: 113-west	1 ½-story, side- gabled Craftsman bungalow open, full- width porch and shed dormer.	С
	22 Brewer Place  Date: 1935 Condition: Excellent Alterations: Rear Addition  TAX MAP: 113-west	2-story, side-gabled, Colonial Revival house with enclosed entry.	С

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	27 Brewer Place  Date: ca. 1940 Condition: Excellent Alterations:	1½ -story, front- gabled, Neo-Colonial house with side wing, gabled dormers, weatherboard and partial stone façade.	C
	TAX MAP: 113-west		
	6 Cass Street  Date: ca. 1920 Condition: Good Alterations:	2½- story, front- gabled, Craftsman house with enclosed front porch.	С
	TAX MAP: 107		
	14 Cass Street Date: c. 1850, 1920s Condition: Good Alterations: Craftsman style renovation of older house.  TAX MAP: 107	2-story, L-shaped vernacular, nineteenth century house with fieldstone foundation made over in 1920s with wood shingles, craftsman porch.	NC
	12 Chase Street  Date: ca. 1920 Condition: Excellent Alterations:	1½-story, cross- gabled, Craftsman "kit" house with front porch, wood shingles and clapboard.	S
	TAX MAP: <b>112</b>		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	10 Chestnut Street  Date: ca. 1840 Condition: Good Alterations: Porch	2-story, brick, front- gabled, Greek Revival house with side wing, 6/6 windows, sidelights, front porch added later.	С
	TAX MAP: <b>111</b>		
	26 Chestnut Street  Date: ca. 1840 Condition: Excellent Alterations: Victorian porch	1½ -story, side- gabled, vernacular house with saltbox roofline, spindlework full-width porch.	С
	TAX MAP: <b>111</b>		
	80 Chestnut Street  Date: ca. 1870 Condition: Good Alterations:  MAP FRAME: <b>B4</b>	2-story, L-shaped, vernacular house with side addition.	С
	104 Chestnut Street	1½-story, front gable	С
	Date: ca. 1840 Condition: Good Alterations:	and wing Greek Revival house with shouldered door surround.	
htm.	MAP FRAME: <b>B4</b>		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	33 Clinton Street Date: ca. 1950 Condition: Good Alterations: Windows, door. Currently occupied by a carpet store.  TAX MAP: 106	1-story, brick church with 1 ½-story front entrance tower, side buttresses, pointed arch windows, glass block cross in tower.	C
	38 Clinton Street  Date: ca. 1850 Condition: Good Alterations: Windows	2 -story, front gable and wing Greek Revival/Italianate with shouldered door and window surrounds.	С
	TAX MAP: <b>108</b>		
	40 Clinton Street  Date: ca.1830 Condition: Good Alterations: Windows  TAX MAP: 108	1½ -story, low- pitched, front-gable and wing Greek Revival house with cornice returns, porch in front of wing, door surround with heavy entablature.	С
	48 Clinton Street  Date: ca. 1920 Condition: Excellent Alterations:	1½ -story, side- gabled, Craftsman bungalow with open front porch and gabled dormer.	S
	TAX MAP: <b>108</b>		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	49 Clinton Street  Date: ca. 1920 Condition: Excellent Alterations:	1½ -story, side- gabled, Craftsman cottage with shed dormer, side entrance porch, 1- story side wing.	S
The second second	TAX MAP: <b>106</b>		
	51 Clinton Street  Date: ca. 1830 Condition: Excellent Alterations: Side porch	2-story, front gable and wing Greek Revival with transom over door, pilasters and entablature.	S
	TAX MAP: <b>106</b>		
	52 Clinton Street  Date: 1920 Condition: Excellent Alterations:	1½-story, side- gabled, Craftsman bungalow with full- width porch contained under main roof, and gabled dormer.	S
	TAX MAP: <b>108</b>		
	55 Clinton Street  Date: mid-19th century Condition: Excellent Alterations: Projecting front wall dormer, Entry porch, Back wing  TAX MAP: 106	1½ -story, side- gabled, vernacular house with projecting front wall dormer and gabled entry porch.	NC

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	11 Colburn Street  Date: ca. 1910 Condition: Excellent Alterations:  TAX MAP: 107	2½ -story, front- gabled, Queen Anne house with polygonal turret, enclosed front porch, probably from a pattern book.	S
	TAX WALL TO		
	16 Colburn Street  Date: ca. 1920 Condition: Excellent Alterations:	2½ -story, side- gabled, Colonial Revival with segmental arch entry porch, small gabled dormer, knee brace brackets.	S
	TAX MAP: <b>107</b>		
	15 Cottage Street  Date: ca. 1920 Condition: Excellent Alterations:	2-story, hipped-roof, Craftsman house with cutaway corner entry, brick and wood shingle siding.	S
	TAX MAP: <b>109</b>		
	18 Cottage Street  Date: ca. 1930 Condition: Excellent Alterations:	2-story, side-gabled, Colonial revival house with entry porch and weatherboard.	С
	TAX MAP: 109-west		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	19 Cottage Street  Date: ca.1880 Condition: Good Alterations: Porch, Rear addition	2½ -story, front- gabled, L-shaped, vernacular house with enclosed front porch.	С
	TAX MAP: <b>109</b>		
	27 Cottage Street  Date: ca. 1890 Condition: Good Alterations:	1½ -story, front- gabled, L-shaped, vernacular house with covered entry at intersection.	С
	TAX MAP: <b>109</b>		
	33 Cottage Street  Date: ca.1880 Condition: Good Alterations: Entry porch  TAX MAP: 109	1½-story, front- gabled, L-shaped vernacular house with board and batten and clapboard siding; entry porch.	С
	18 Crandall Street  Date: ca.1920 Condition: Excellent Alterations:	2-story, hipped-roof, American Foursquare, full- width porch and clapboard siding.	С
	TAX MAP: 113-west		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	223 East Main Street (US 20)  Date: ca. 1920 Condition: Excellent Alterations:  MAP FRAME: A4	2½ -story, hipped- roof, American Foursquare with craftsman detailing and enclosed porch.	C
	270 East Main Street (US 20)  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 110	1½-story, side- gabled, Craftsman Bungalow with front porch contained under roof, gabled dormer.	S
	279 East Main Street  Date: ca. 1920 Condition: Excellent Alterations:  MAP FRAME: A4	2½-story, deck on hip roof, Colonial Revival with gabled dormers and wrap- around porch.	S
	19 East Pearl Street  Date: ca. 1870 Condition: Fair Alterations: Windows, Porch  TAX MAP: 107	2 ½-story, L-shaped, clipped-end gables, Victorian Eclectic house with segmental window hoods; wrap-around front porch added.	С

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	68 Elm Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 113-west	2-story, hipped-roof, brick, Colonial Revival house with covered entry.	S
	70 Elm Street Date: ca.1920 Condition: Excellent Alterations:  TAX MAP: 113-west	1½ -story, side- gabled, Craftsman bungalow with enclosed front porch and front gabled dormer.	S
	72 Elm Street  Date: ca.1920 Condition: Excellent Alterations: Attached garage  TAX MAP: 113-west	2-story, side-gabled, Colonial Revival house, central entrance bay with gabled wall dormer.	S
	87 Elm Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 114-west	2½-story, hipped- roof, Colonial Revival house with canopy over entrance and one story side enclosed porch	S

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	106 Elm Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 114-west	2-story, pyramidal- roof, Craftsman house with front porch, stucco, quoins.	C
	110 Elm Street Date: 1920 Condition: Excellent Alterations:  TAX MAP: 114-west	2½ -story, side- gabled, Craftsman/ Colonial house with open, full-width porch, sheathed with wood shingles.	S
	112 Elm Street  Date: 1920 Condition: Excellent Alterations: Windows  TAX MAP: 114-west	1½ -story, front- gabled, Craftsman bungalow with roof brackets, shed roof side wall dormer and recessed corner entrance.	S
	114 Elm Street  Date: 1920 Condition: Excellent Alterations:	1½ -story, cross- gabled, Craftsman bungalow with front porch and wood shingle siding.	S
	TAX MAP: 114-west		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	Date: ca.1920 Condition: Excellent Alterations:  TAX MAP: 114-west	1-story, front-gabled, Craftsman Bungalow with full-width, gabled porch and roof brackets, side facing wall dormer, and weatherboard siding.	S
	121 Elm Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 114-west	2½ -story, hipped- roof, American Foursquare with front porch and projecting side facing wall dormer over a projecting bay.	S
	125 Elm Street  Date: ca. 1945 Condition: Excellent Alterations:  TAX MAP: 114-west	1-story, front-gabled, Lustron house, intact, aqua example of the mass- produced houses made for a short time after WWII by the Lustron Corporation in Columbus, OH. These houses came in only 6 colors.	S
	40English Street  Date: ca. 1890 Condition: Fair Alterations:  TAX MAP: 107	1-story, lumber warehouse with monitor roof and clapboard siding. Poured concrete storage bunker attached to east side.	С

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	25 First Street  Date: ca. 1890 Condition: Excellent Alterations:  TAX MAP: 113-west	2½ -story, front- gabled, Queen Anne house with wraparound porch, clapboard and wood shingle siding.	S
	26 First Street  Date: ca.1920 Condition: Excellent Alterations:  TAX MAP: 113-west	1½ -story, side- gabled Craftsman bungalow with enclosed, front porch and front facing gabled dormer.	S
	29 First Street  Date: ca. 1920 Condition: Good Alterations: Windows  TAX MAP: 113-west	2-story hipped-roof, American Four- square with enclosed front porch and clapboard siding.	S
	17 Franklin Street  Date: ca. 1860 Condition: Good Alterations:  TAX MAP: 106	2-story, L-shaped, vernacular house with side wing and enclosed entry porch.	С

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	29 Franklin Street  Date: ca. 1860 Condition: Good Alterations:	2½ -story, L-shaped, vernacular house with segmental arched window surrounds, spindlework porch with unusual detail, gabled dormer.	S
	TAX MAP: <b>106</b>		
	36 Franklin Street  Date: ca.1870 Condition: Good Alterations:	2 ½-story, L-shaped, vernacular house with simple front porch and gabled dormer.	С
	TAX MAP: <b>106</b>		
	45 Franklin Street  Date: ca. 1840 Condition: Good Alterations: Wood shingles, windows, porch	1½ -story, front gable and wing, Greek Revival house with gabled entry porch.	С
	TAX MAP: <b>106</b>		
	46 Franklin Street  Date: ca. 1850 Condition: Good Alterations: enclosed porch	2-story, hipped-roof, Italianate house with 2-story side-wing, and roof brackets. Porch addition has enclosed first story and open second story.	С
	TAX MAP: <b>106</b>		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	9 Grove Street  Date: ca. 1920 Condition: Excellent Alterations: Side addition	2-story, side-gabled, Colonial Revival house with 1-story side addition and enclosed front porch.	C
	TAX MAP: <b>109</b>		
	31 Grove Street  Date: ca. 1880 Condition: Good Alterations: Windows	2-story front gabled, vernacular house with enclosed side porch. It has a small 1½ -story, single bay, carriage house.	С
	TAX MAP: <b>109</b>		
	33 Grove Street  Date: 1880 Condition: Good Alterations:	2-story, front-gabled, vernacular house with enclosed front porch.	С
	TAX MAP: <b>109</b>		
	34 Grove Street  Date: ca. 1870 Condition: Fair Alterations:	2-story, L-shaped, front-gabled, vernacular house with enclosed porch at intersection, clapboard siding.	С
	TAX MAP: <b>109</b>		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	8419 Hawley Street  Date: ca. 1830 Condition: Excellent Alterations: Rock-faced concrete block porch foundation.  MAP FRAME: A4	A high-style, intact example of a 1-story Greek Revival house with temple front. The occurrence of this Greek Revival sub-type is limited. Temple fronts in this area are generally 2-story.	S
	17 Holt Street Date: 1920 Condition: Good Alterations: Windows, Porch  TAX MAP: 107	2-story, hipped-roof American Foursquare with hipped dormer.	NC
	29 Holt Street  Date: 1920s Condition: Good Alterations: Windows, Porch  TAX MAP: 107	1 ½-story, front- gabled, Craftsman bungalow with enclosed front porch, and wood shingles.	С
	31 Jefferson Street  Date: ca. 1858 Condition: Excellent Alterations: Front porch, parts of cornice removed, slate roof coated in asphalt.  No NR determination.  TAX MAP: 106	1 ½-story, brick, Italianate/2 <sup>nd</sup> Empire house with mansard roof, concrete block porch added in early 20 <sup>th</sup> century.	S

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	42 Jefferson Street  Date: ca. 1870 Condition: Excellent Alterations:	2½ -story, front- gabled, Queen Anne house with delicate spindlework porch.	C
	TAX WAP. 100		
	47 Jefferson Street  Date: ca. 1870 Condition: Good Alterations:	2-story, front gable and wing vernacular house with hipped- roof projecting bay on gable end.	С
	TAX MAP: <b>106</b>		
	88 Jefferson Street  Date: ca. 1920 Condition: Good Alterations: Front porch  TAX MAP: <b>107</b>	2-story, hipped-roof, American Foursquare with concrete block walls and porch foundation, hipped dormer.	С
	91 Jefferson Street	11/ story front	С
	Date: ca. 1830 Condition: Good Alterations: Windows, Entry	1½ -story, front- gabled, Greek Revival house with with rear wing.	
	TAX MAP: <b>107</b>		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	23 Kent Street  Date: 1920 Condition: Excellent Alterations:	2-story, pyramidal- roofed, Craftsman house with wood shingles and side porch.	S
	TAX MAP: 113-west		
	27 Kent Street  Date: ca. 1920 Condition: Excellent Alterations:	1½ -story, clipped side-gabled, Colonial Revival house with shed roof dormer and wood shingles.	Ø
	TAX MAP: 113-west		
	28 Kent Street  Date: ca. 1920 Condition: Excellent Alterations:	1½ -story, side- gabled, Craftsman bungalow with side entrance, wood shingles, segmental- arched windows, 1- story enclosed side porch, and shed dormer.	S
	TAX MAP: 113-west		
	29 Kent Street  Date: ca. 1920 Condition: Excellent Alterations:	1-story, front-gabled, Craftsman bungalow with ½ width gabled front porch and wood shingles.	S
	TAX MAP: 113-west		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	31 Kent Street  Date: ca. 1920 Condition: Excellent Alterations:	1 ½-story, front- gabled, Craftsman bungalow with full- width porch and weatherboard siding.	C
	TAX MAP: 113-west		
	32 Kent Street  Date: ca. 1920 Condition: Excellent Alterations:	1½ -story, front- gabled Tudor Revival house with side wing and lower gable above arched front door, brick and shingle.	S
	TAX MAP: 113-west		
	28 McClurg Street  Date: ca. 1920 Condition: Good Alterations:  TAX MAP: 113-west	1½ -story, front- gabled house with front porch with brick piers, brick first story and wood shingle on upper story, half- timbering in gable end, side-facing, shed wall dormer.	S
	31 McClurg Street  Date: ca.1920 Condition: Good Alterations: Windows	2-story, hipped-roof, Craftsman house with half-width front porch, stucco and raised concrete block foundation.	S
	TAX MAP: 113-west		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	32 McClurg Street  Date: ca. 1920 Condition: Excellent Alterations:	2-story, hipped-roof, Colonial Revival residence with Craftsman influence, front porch, simple brackets under wide eaves, brick.	S
The state of the s	TAX MAP: 113-west		
	150 North Portage Rd. (NY 394) Date: ca. 1920 Condition: Fair Alterations: Windows	2-story, brick, cross- gabled, vernacular house with wrap- around front porch.	NC
	MAP FRAME: <b>A4</b>		
	173 North Portage Road (NY 394)  Date: ca. 1920 Condition: Good Alterations: Windows	2½-story, brick, hipped-roof, American Foursquare, with full- width porch and hipped dormer.	С
	MAP FRAME: <b>A4</b>		
	Westfield(V); east side of North Portage (NY 394), just south of NYS 90  Date: ca. 1890 Condition: Good Alterations: Porch	2½-story, brick, front- gabled, vernacular house with front porch and segmental arched window openings on side elevations.	С
	MAP FRAME: <b>A4</b>		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	21 North Water Street  Date: Condition: Excellent Alterations:	2-story, side-gabled, 4- by 2-bay, house with symmetrical fenestration, one- story side wing.	С
The second secon	TAX MAP: <b>105</b>		
	21A North Water Street  Date: ca. 1870 Condition: Good Alterations:	Large 2-story, front- gabled, barn with sliding wagon doors in end gable, board and batten siding, 6/6 double-hung wood sash, Roof	S
	TAX MAP: <b>105</b>	slope labeled "John Kutz Nursery."	
	Westfield(V); north side of Old Hawley, west of N. Portage Rd (NY 394)  Date: ca. 1880 (barn) Condition: Excellent Alterations: Its associated house is highly modified (ca. mid-19 <sup>th</sup> century)	This property is notable for its barn, which is a side gabled-, 3-bay, bank barn with entry on barn side. It has board and batten siding and multiple windows.	S
	MAP FRAME: <b>A4</b> 21 Pearl Street	2-story, front-gabled,	С
	Date: ca. 1860 Condition: Good Alterations:	Gothic Revival/ Italianate house with gabled wall dormer, spindlework, full- width porch.	J
	TAX MAP: <b>107</b>		

Photo	Address/Date/Condition/	Description	Rating
	Alterations 31 Pearl Street  Date: ca. 1890 Condition: Good Alterations: Foundation  TAX MAP: 107	2½ -story, cross- gabled, Queen Anne house with spindlework wrap- around porch.	S,C,NC C
	34 Pearl Street  Date: ca. 1940 Condition: Good Alterations: Cupola altered, Concrete block additions. Modified for the VFW.  TAX MAP: 106	1½ -story, hipped- roof, Greek/Italianate transitional building with cupola.	S
	35 Pearl Street Date: 1920s Condition: Good Alterations: Porch  TAX MAP: <b>107</b>	1-story, front-gabled, Craftsman bungalow with added front porch.	С
	24 Pleasant Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 113-east	1½ -story, sidegabled, Craftsman bungalow with ½ with partial porch porch and shed dormer.	S

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	28 Pleasant Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 113-east	1½ -story, side- gabled, Craftsman style "kit" house with gabled wall dormer and open, full-width porch. Dormer and gable ends have pointed arch.	S
	25 Second Street  Date: ca. 1850 Condition: Good Alterations: Windows, porch  TAX MAP: 113-west	1½ -story, front- gabled, with side wing Greek Revival house, sheathed with wood shingles.	C
n/a	28 Second Street  Date: ca.1920 Condition: Good Alterations: Windows  TAX MAP: 114-west	2½ -story, side- gabled, Craftsman house with wood shingles.	С
	30 Second Street  Date: 1850 Condition: Excellent Alterations: Front porch  TAX MAP: 114-west	1½ -story, front- gabled, Greek Revival house with full-width porch.	С

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	22 South Gale Street  Date: ca.1890 Condition: Excellent Alterations:  MAP FRAME: <b>B4</b>	2½ -story, front- gabled, Queen Anne house with projecting, front- gabled bay, open full-width porch, gabled wall dormer.	S
	22A South Gale Street  Date: ca. 1880 Condition: Good Alterations: Garage doors  MAP FRAME: <b>B4</b>	Front-gabled, carriage house converted to garage with board and batten siding.	С
	11 South Water Street  Date: ca. 1850 Condition: Excellent Alterations: Entry porch  No NR determination.  TAX MAP: 112	1½ -story, front-gable and wing Greek Revival /Italianate house with shouldered window surrounds and cornice returns.	S
	15 South Water Street  Date: ca. 1830 Condition: Excellent Alterations: Shed roof side addition  No determination.  TAX MAP: 112	1 ½-story, side- gabled, Greek Revival house, center entrance heavy entablature, side addition including front enclosed porch.	S

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	25 South Water Street  Date: ca. 1830 Condition: Excellent Alterations:  No determination.  TAX MAP: 112	2-story, side-gabled, Federal style house with unusual pattern along cornice line, fanlight with entablature over center entrance door.	S
	33 South Water Street  Date: ca. 1840 Condition: Excellent Alterations: Side addition, porch  No NR determination.  TAX MAP: 112	1½ -story, front- gabled, Greek revival house with shed side addition and front porch.	S
	18 Spring Street  Date: ca. 1870 Condition: Excellent Alterations:  TAX MAP: 113-east	2-story, front-gabled, L-shaped, vernacular house with wood shingles and an enclosed porch.	С
	18A Spring Street  Date: ca.1890 Condition: Excellent Alterations:  TAX MAP: 113-east	1½ -story, front- gabled, carriage house with side wing.	С

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	19 Spring Street  Date: ca. 1850 Condition: Excellent Alterations:  TAX MAP: 113-east	1½ -story, front- gabled, Italianate house with side wing and porch.	S
	19A Spring Street  Date: 1880 Condition: Good Alterations: Door	1½- story, carriage house with fan light in front gable peak.	S
	TAX MAP: 113-east		
	22 Spring Street  Date: ca. 1850 Condition: Excellent Alterations:  TAX MAP: 113-east	2-story, front-gabled Italianate house with 1-story side wing and front porch, round arch windows with hoods, double leaf door with glazed, round- arched transom above,	S
		polygonal bay.	
	50 Spring Street  Date: ca. 1860 Condition: Good Alterations: Entry porch	2-story, front-gabled vernacular house with side-entry porch and clapboard siding.	С
	TAX MAP: 113-east		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	56 Spring Street  Date: ca. 1860 Condition: Good Alterations: porch, windows  TAX MAP: 114-east	2-story, front-gabled, L-shaped, vernacular house with porch and shouldered window surrounds.	C
	64 Spring Street  Date: ca.1890 Condition: Excellent Alterations:  TAX MAP: 114-east	2 ½-story, front- gabled, L-shaped Queen Anne house with wrap-around porch.	S
	64A Spring Street  Date: ca. 1890 Condition: Good Alterations: Side additions  TAX MAP: 114-east	2½ -story, front gabled carriage house with shed- and flat-roofed additions.	S
	69 Spring Street  Date: ca. 1850 Condition: Good Alterations: Windows  TAX MAP: 114-east	2-story, front-gabled, L-shaped vernacular house with porch in front of wing and clapboard siding.	С

Alterations	Description	Rating S,C,NC
72 Spring Street  Date: ca.1920 Condition: Excellent Alterations:	2-story, side gabled, Colonial style "kit house" with front gabled wall dormer, entry porch, wood shingle and clapboard siding.	S
TAX WAF. 114-east		
79 Spring Street  Date: ca.1830 Condition: Good Alterations: Wood shingles, rear addition  TAX MAP: 114-east	1½ -story, side- gabled, vernacular house with rear wing and shouldered window surrounds.	С
13 Union Street  Date: ca. 1920 Condition: Excellent Alterations: Upper floor windows  TAX MAP: 114-west	2-story front-gabled, Craftsman cottage with front porch, brackets and wood shingles.	S
14 Union Street  Date: ca.1920 Condition: Excellent  TAX MAP: 114-west	2-story, front-gabled, Craftsman house with enclosed front porch, brick and wood shingles.	S
	Date: ca.1920 Condition: Excellent Alterations:  TAX MAP: 114-east  79 Spring Street  Date: ca.1830 Condition: Good Alterations: Wood shingles, rear addition  TAX MAP: 114-east  13 Union Street  Date: ca. 1920 Condition: Excellent Alterations: Upper floor windows  TAX MAP: 114-west  14 Union Street  Date: ca.1920 Condition: Excellent  Alterations: Upper floor windows	Colonial style "kit house" with front gabled wall dormer, entry porch, wood shingle and clapboard siding.  TAX MAP: 114-east  79 Spring Street  Date: ca.1830 Condition: Good Alterations: Wood shingles, rear addition  TAX MAP: 114-east  13 Union Street  Date: ca. 1920 Condition: Excellent Alterations: Upper floor windows  TAX MAP: 114-west  14 Union Street  Date: ca.1920 Condition: Excellent Alterations: Upper floor windows  2-story front-gabled, Craftsman cottage with front porch, brackets and wood shingles.  2-story, front-gabled, Craftsman house with enclosed front porch, brick and wood shingles.

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	15 Union Street Date: 1915 Condition: Excellent Alterations: Entrance TAX MAP: 113-west	St James Major Roman Catholic Church has a 3-story central tower, round arch windows, stone window hoods and buttresses.	S
	19 Union Street  Date: ca. 1850 Condition: Excellent Alterations: Windows, Entrance  TAX MAP: 113-west	First Baptist Church is a rectangular, brick, 1-story Italianate with corbelled corner piers, pilasters and cornice. It appears that the brick false front suggesting a pediment and central tower was added later.	S
	18 Union Street  Date: ca. 1920 Condition: Excellent  TAX MAP: 113-west	1½ -story, Craftsman bungalow with side-gabled roof, large front gabled dormer, full-width porch, brick and wood shingles.	С
	20 Union Street  Date: ca. 1920 Condition: Excellent Alterations: Windows  TAX MAP: 113-west	2-story, hipped-roof, Craftsman-American Foursquare with hipped dormer, front porch arched entry and side bays, and wood shingles	С

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	22 Union Street  Date: ca. 1920 Condition: Excellent Alterations: Some vinyl on first story.  TAX MAP: 113-west	2-story, hipped-roof, Craftsman-American Foursquare craftsman with hipped dormer, full- width porch and wood shingles.	C
	24 Union Street  Date: ca.1920 Condition: Excellent Alterations:  TAX MAP: 113-west	2-story, hipped-roof, Craftsman -American Foursquare with hipped dormer, clapboard siding, and front porch with rock faced concrete block.	С
	26 Union Street  Date: ca. 1920 Condition: Good Alterations: Windows  TAX MAP: 113-west	2-story, hipped-roof, Colonial Revival house with wood shingles and second story porch.	С
	39 Union Street  Date: ca.1885 Condition: Excellent Alterations: Windows  TAX MAP: 113-west	2½ -story, front gable on hip, Queen Anne with clapboard siding and portico over entrance.	S

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	42 Union Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 113-west	1½ -story, Craftsman bungalow with hip on hip roof, enclosed front porch, concrete block first story, clapboard on upper story.	S
	44 Union Street  Date: ca.1920 Condition: Excellent Alterations:  TAX MAP: 113-west	1½ -story, sidegabled, Craftsman bungalow with shed dormer, front porch, brick and wood shingle siding.	S
	45 Union Street  Date: ca. 1840 Condition: Excellent Alterations: Porch, Side wings, Widows, Dormer  TAX MAP: 113-west	1½ -story, front- gabled, Greek Revival block with 1- story additions on each side, front porch and side dormer also added.	С
	52 Union Street Date: ca.1950  Condition: Excellent Alterations:  TAX MAP: 113-west	1½ -story, side- gabled, Colonial Revival house with weatherboard siding and front porch.	NC

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	59 Union Street  Date: ca. 1890 Condition: Good Alterations:  TAX MAP: 113-west	1½ -story, L-shaped, vernacular house.	С
	62 Union Street  Date: ca. 1890 Condition: Good Alterations:  TAX MAP: 113-west	2-story, front-gabled, vernacular house with front and side porches with turned posts, side polygonal bay, clapboard siding.	C
	77 Union Street  Date: ca. 1890 Condition: Good Alterations: Windows, Porch  TAX MAP: 114-west	2½ -story, front- gabled main block with side wing and rear addition, porch in front of wing.	С
	89 Union Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 114-west	1½ -story, hipped- roof, Craftsman bungalow, front- and side- gabled dormers, and recessed corner entry porch.	S

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	91 Union Street  Date: ca. 1920 Condition: Excellent Alterations:  TAX MAP: 114-west	1½ -story, side- gabled Craftsman bungalow with front hipped dormer and recessed corner entry porch. False timbering in gable ends.	S
	Old St. James Cemetery Westfield (V); east side of Union Street, southern terminus  Date: ca. 1840 Condition: Excellent  TAX MAP: 117	Small cemetery located in the southern limits of the village.	S
	11 Washington Street  Date: ca. 1840 Condition: Good Alterations: Porch  TAX MAP: 106	2-story, side-gabled, brick vernacular house with transom window, segmental arch window surrounds.	С
	23 Washington Street  Date: ca. 1850 Condition: Fair Alterations: Porch  TAX MAP: 106	2-story, L-shaped, Italianate/vernacular house with clapboard siding, and concrete block front porch.	С

Address/Date/Condition/ Alterations	Description	Rating S,C,NC
51 Washington Street  Date: ca. 1880 Condition: Excellent Alterations:  TAX MAP: <b>106</b>	2-story, brick, L-shaped, Queen Anne house with gabled front and corner projecting bays, front entry porch, side porch with turned posts.	S
56 Washington Street  Date: ca. 1840 Condition: Good Alterations: Windows  TAX MAP: 106	1½ -story, front gable and wing Greek Revival house with enclosed porch in front of wing, shouldered door surround with heavy entablature, recessed door, wood shingles.	С
58 Washington Street  Date: 1840s Condition: Good Alterations:  TAX MAP: 106	1½-story, front gable and wing Greek Revival with porch in front of wing, door surround with pilasters and heavy entablature, recessed door, dentil cornice, wood shingles.	Ø
6 Wells Street  Date: 1920 Condition: Good Alterations:  TAX MAP: 113-east	2-story, front-gabled, L-shaped house with porch in front of wing and wood shingles.	С
	Alterations 51 Washington Street  Date: ca. 1880 Condition: Excellent Alterations:  TAX MAP: 106  56 Washington Street  Date: ca. 1840 Condition: Good Alterations: Windows  TAX MAP: 106  58 Washington Street  Date: 1840s Condition: Good Alterations:  TAX MAP: 106  6 Wells Street  Date: 1920 Condition: Good Alterations:	Alterations  51 Washington Street  Date: ca. 1880 Condition: Excellent Alterations:  TAX MAP: 106  56 Washington Street  Date: ca. 1840 Condition: Good Alterations:  TAX MAP: 106  58 Washington Street  Date: ca. 1840 Condition: Good Alterations: Windows  TAX MAP: 106  58 Washington Street  Date: 1840s Condition: Good Alterations: Windows  TAX MAP: 106  58 Washington Street  Date: 1840s Condition: Good Alterations:  TAX MAP: 106  58 Washington Street  Date: 1840s Condition: Good Alterations:  TAX MAP: 106  58 Washington Street  Date: 1920 Condition: Good Alterations:  TAX MAP: 106  Condition: Good Alterations:  Condition: Good Alterations:  Alterations:  Date: 1920 Condition: Good Alterations:  Alterations:

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	8 Wells Street  Date: ca. 1920 Condition: Good Alterations: Porch  TAX MAP: 113-east	2-story, front-gabled, Craftsman house with full-width porch, wood shingles.	C
	155 West Main Street (US 20)  Date: ca. 1880 Condition: Good Alterations:  TAX MAP: <b>104</b>	2½ -story, gabled, T-shaped Queen Anne house with spindlework porch.	С
	161 West Main Street (US 20)  Date: ca. 1880s Condition: Excellent Alterations:  TAX MAP: 104	2 ½-story, L-shaped Queen Anne house with wrap-around porch. Large, front- gabled carriage house barn has been converted.	S
	171 West Main Street (US 20)  Date: ca. 1850 Condition: Good Alterations: Porch  MAP FRAME: <b>B4</b>	2-story, front gable and wing Greek Revival house. Paired, slender round-arched windows show Italianate influence. Porch in front of wing was added.	С

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	205 West Main Street (US 20)  Date: ca. 1830 Condition: Good Alterations: Vinyl siding, windows, porch  MAP FRAME: <b>B4</b>	2-story, front-gabled, Greek Revival with wing. Door has entablature, wing has front porch with spindlework detail. This property is notable for its barn, see below.	NC NC
	205A West Main Street (US 20)  Date: ca. 1870 Condition: Good Alterations: Garage door  MAP FRAME: B4	1½ -story, 3-bay, side-gabled, barn with unusual elliptical fanlight above the main door, smaller side door flanked by windows -all with elliptical arches above.	S
	19 West Second Street  Date: ca. 1890 Condition: Excellent Alterations:  TAX MAP: 112	2-story, T-shaped, gabled, Victorian house with enclosed porch at intersection, three-sided bays with shed roof and brackets.	С
	32 West Second Street  Date: ca. 1830 Condition: Good Alterations: Entry porch	1½ -story, front- gabled, Greek Revival house with exposed rafter tail ends.	С
	TAX MAP: 112		

Photo	Address/Date/Condition/ Alterations	Description	Rating S,C,NC
	11 Wood Street  Date: ca. 1840s Condition: Excellent Alterations:	2-story, front-gabled, Italianate house with side wing and porch, segmental arched windows.	S
	TAX MAP: <b>114-west</b>		