



HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 17 C Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: single-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known c.1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **17 C Street** is located on the south side of a one-block long, east-west street between Fillmore Avenue and Mills Street. C Street is located in the north-central section of the Broadway-neighborhood. It is one of three "letter" streets between Genesee and Sycamore Streets. A vacant lot is located on the east side of the property. The surrounding area is densely built-up with early twentieth century residences. Martin Luther King, Jr. Park is located five blocks to the north.

A one-and-one-half story, frame, extended- workers' cottage with a broad front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width Craftsman porch with square columns and wood-shingled solid rail. The first floor façade has a main entrance in the east bay and a Craftsman-type, triple window-grouping. Exterior wall fabrics are wood shingle and clapboard. Fenestration is one-over-one, double-hung wood sash and casement. The west slope has a shed dormer. A brick chimney rests on the rear ridge. A single-bay garage stands at the southwest corner of the lot.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 17 C Street is significant **as** a good representative example of a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. Built as a one family dwelling, it was enlarged to the rear for Charles Laudes' milk dairy in 1912. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 292



N

PHOTOGRAPH: (Broadway-Fillmore R-6; N-8)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____
Address or Street Location 20 C Street
County Erie Town/City Buffalo Village/Hamlet: _____
Owner _____ Address _____
Original use Residence: single-family Current use Residence: single-family
Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **20 C Street** is located on the north side of a one-block long, east-west street between Fillmore Avenue and Mills Street. C Street is located in the north-central section of the Broadway-neighborhood. It is one of three "letter" streets between Genesee and Sycamore Streets. The surrounding area is densely built-up with early twentieth century residences. Martin Luther King, Jr. Park is located five blocks to the north.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width Craftsman-detailed porch that includes square columns, a gabled roof with wood-shingles and exposed rafter tail ends. The first floor façade has a main entrance in the west bay and a triple-window grouping in the east bay. Exterior wall fabrics are wood shingle and clapboard. Fenestration is one-over-one, double-hung wood sash. The west elevation has a gabled wall dormer. A brick chimney rests on the rear ridge.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at **20 C Street** is significant as a good representative example of a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 292



PHOTOGRAPH: (Broadway-Fillmore R-6; N-9)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 35 C Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1885

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: _____ Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The multiple-family house at **35 C Street** is located on the south side of a one-block long, east-west street between Fillmore Avenue and Mills Street. C Street is located in the north-central section of the Broadway-neighborhood. It is one of three "letter" streets between Genesee and Sycamore Streets. A vacant lot is located on the east side of the property. The surrounding area is densely built-up with early twentieth century residences. Martin Luther King, Jr. Park is located five blocks to the north.

A two-and-one-half story, front-gabled, frame, vernacular residence with no foundation. It has a rectangular plan. Exterior wall fabric is clapboard. The façade has a full-width porch with square columns, a metal rail, and an ornamental concrete block foundation. The entrance with $\frac{3}{4}$ sidelights is located in the west bay. Fenestration is one-over-one, double-hung wood sash. The upper façade has an open porch with metal balustrade and an entry door in the west bay. A small one-over-one double-hung sash window punctuates the gable peak. Other architectural details include Eastlake molding beneath the front gable eaves, and a polygonal bay with brackets on the east elevation. A brick chimney rests on east slope.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 35 C Street is significant as a good representative example of a two-story, late nineteenth century workers' cottage with Craftsman details. A second story was added to this house by George Heibach in 1893. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 292



PHOTOGRAPH: (Broadway-Fillmore R-6; N-10)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION & HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____
Address or Street Location 40 C Street
County Erie Town/City Buffalo Village/Hamlet: _____
Owner _____ Address _____
Original use Residence: single-family Current use Residence: single-family
Architect/Builder, if known _____ Date of construction, if known ca. 1882

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation: stone brick poured concrete concrete block

Other materials and their location: _____

Alterations, if known: _____ Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **40 C Street** is located on the north side of a one-block long, east-west street between Fillmore Avenue and Mills Street. C Street is located in the north-central section of the Broadway-neighborhood. It is one of three "letter" streets between Genesee and Sycamore Streets. The surrounding area is densely built-up with early twentieth century residences. Martin Luther King, Jr. Park is located five blocks to the north.

A one-and-one-half story, frame workers' cottage with a broad front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width, Craftsman porch with battered, square, paneled piers set on square, wood-shingled pedestals, and a gabled-roof with wood shingles. The original porch rail has been replaced. The main entrance is in the west bay. Exterior wall fabrics are wood shingle and clapboard. Fenestration is one-over-one, double-hung wood sash and casement. The gable end has a paired window grouping with pent. The east slope has a shed dormer. A brick chimney is located rear, off-center ridge.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 40 C Street is significant as a largely intact, excellent example of a late nineteenth century, workers' cottage with early twentieth century Craftsman detailing. This house was enlarged in 1906 for John Guilder; the prominent dormer was added in 1931 for Anthony Rynwalski. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 292



PHOTOGRAPH: (Broadway-Fillmore R-6; N-11)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 47 C Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1892

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: _____ Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **47 C Street** is located on the south side of a one-block long, east-west street between Fillmore Avenue and Mills Street. C Street is located in the north-central section of the Broadway-neighborhood. It is one of three "letter" streets between Genesee and Sycamore Streets. A vacant lot is adjacent to the west side of the property. The surrounding area is densely built-up with early twentieth century residences. Martin Luther King, Jr. Park is located five blocks to the north. A vacant lot borders the property to the west.

A one-and-one-half story, front-gabled, frame, extended workers' cottage with no foundation. It has a rectangular plan and no basement. The façade has an entrance with a Craftsman-type door in the west bay, with a modern stoop. Exterior wall fabrics are clapboard and wood shingle. Fenestration is one-, and two-over-one, double-hung wood sash. The first floor façade windows have the original leaded glass in the headers. Eastlake molding accents the front gable eaves. Extending south from the north end of the main block are two one-story, gabled-roof additions. Brick chimneys rest on the front, off-center ridge center ridge of the main block and on the center ridge of the rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 47 C Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1886) – Plate 292



PHOTOGRAPH: (Broadway-Fillmore R-6; N-12)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____
Address or Street Location 49 C Street
County Erie Town/City Buffalo Village/Hamlet: _____
Owner _____ Address _____
Original use Residence: single-family Current use Vacant
Architect/Builder, if known _____ Date of construction, if known c.1900

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: _____ Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The building at **49 C Street** is located on the south side of a one-block long, east-west street between Fillmore Avenue and Mills Street. C Street is located in the north-central section of the Broadway-neighborhood. It is one of three "letter" streets between Genesee and Sycamore Streets. The surrounding area is densely built-up with early twentieth century residences. The Church of the Transfiguration is located immediately to the south on Sycamore Street. Martin Luther King, Jr. Park is located five blocks to the north.

A one-and-one-half story, front-gabled, workers' cottage with no foundation. It has a rectangular plan. The main entrance and porch are located on the east elevation of the one-bay-wide cottage. The house appears not to have been completed, as it is comprised of only the rear section of what resembles the extended cottage. Exterior wall fabric is clapboard. The window openings have been boarded. A gabled-dormer rests on the east slope and brick chimney is located rear ridge. A single- bay, front-gabled garage sheathed with clapboard stands at the southeast corner of the lot.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 49 C Street is significant as a good representative example of a workers' cottage that consists of just the rear section. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 292



PHOTOGRAPH: (Broadway-Fillmore R-6; N-13)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 53 C Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca.1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **53 C Street** is located on the south side of a one-block long, east-west street between Fillmore Avenue and Mills Street. C Street is located in the north-central section of the Broadway-neighborhood. It is one of three "letter" streets between Genesee and Sycamore Streets. The surrounding area is densely built-up with early twentieth century residences. The Church of the Transfiguration is located immediately to the south on Sycamore Street. Martin Luther King, Jr. Park is located five blocks to the north.

A one-and-one-half story, front-gabled, extended workers' cottage with no foundation. It has a rectangular plan. The main entrance with a modern replacement stoop is located in the west bay. Exterior wall fabric is clapboard. Fenestration is one-over-one double-hung wood sash. The façade window openings have simple hoods. Eastlake molding accents the gable end. Two, one-story additions extend from the south end of the main block. Brick chimneys are located on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 53 C Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1886) – Plate 292



PHOTOGRAPH: (Broadway-Fillmore R-6; N-14)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 63 C Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known 1888

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The multiple-family house at **63 C Street** is located on the south side of a one-block long, east-west street between Fillmore Avenue and Mills Street. C Street is located in the north-central section of the Broadway-neighborhood. It is one of three "letter" streets between Genesee and Sycamore Streets. A vacant lot is located to the west of the property. The surrounding area is densely built-up with early twentieth century residences. The Church of the Transfiguration is located immediately to the south on Sycamore Street. Martin Luther King, Jr. Park is located five blocks to the north.

A two-and-one half story, front-gabled, frame, vernacular residence with no foundation. It has a rectangular plan and no basement. Exterior wall fabric is clapboard. The façade has an entrance with modern stoop in the east bay. Fenestration is one-over-one, double-hung wood sash and casement. Other architectural details include corner boards and Eastlake molding. A one-story addition with recessed entry porch extends south from the south end of the main block. A brick chimney rests on the west slope.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 63 C Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 292



PHOTOGRAPH: (Broadway-Fillmore R-6; N-15)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 34 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: single-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1885

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **34 Clark Street** is located on the west side of the southern end of street, between Memorial Drive and Peckham Street. Clark Street is a five-block long residential street between Broadway and Memorial Drive. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal stands directly to the east.

A one-and-one-half story, front-gabled, frame, extended workers' cottage with no foundation. It has a rectangular plan. The façade has an entry door with a bracketed canopy and a modern stoop located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash. Extending west from the west end of the main block are two one-story, gabled-roof additions. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 34 Clark Street as a good representative example of a late nineteenth century, extended workers' cottage. It was enlarged for Enlarged for John Jankowiak in 1904. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 211



PHOTOGRAPH: (Broadway-Fillmore R-11; N-12)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 92 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known 1892

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation: stone brick poured concrete concrete block

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The two-family house at **92 Clark Street** is located on the west side of the southern end of the street, between Peckham and Paderewski streets. Clark Street is a five-block long, north-south, residential street between Broadway and Memorial Drive. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal stands directly to the east.

A two-story, closed-gabled, frame, extended workers' cottage with no foundation. It has a rectangular plan. The façade has Craftsman-detailed full-width porch with a rusticated block foundation, battered, square, paneled supports and a wood-shingled pediment. The original porch rail has been replaced. The main entrance is located in the north bay. Exterior wall fabrics are clapboard and wood shingle. Fenestration is casement and one-over-one, double-hung wood sash. An oriel is located on the south side. Extending west from the west end of the main block are two one-story, gabled-roof additions with entries and gabled dormers on the south elevation. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 92 Clark Street is significant as a good representative example of an extended workers' cottage that was enlarged to two-stories. The house received an addition in 1914 and the front section was raised from one-story to two-stories in 1919; the porch was likely added at this time. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 204



PHOTOGRAPH: (Broadway-Fillmore R-11; N-11)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 152 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **152 Clark Street** is located on the west side of the street, between Paderewski and S. Market streets. Clark Street is a five-block long residential street between Broadway and Memorial Drive. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal stands to the southeast.

A one-and-one-half story, front-gabled, frame, extended workers' cottage with no foundation. It has a rectangular plan. The façade has an entry door and a modern stoop located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash. Extending west from the west end of the main block are two one-story, gabled-roof additions with side entrances. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 152 Clark Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 204



PHOTOGRAPH: (Broadway-Fillmore R-11; N-10)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) Corpus Christi Roman Catholic Church

Address or Street Location 161 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Religious Current use Religious

Architect/Builder, if known Schmill & Gould, architects Date of construction, if known 1906-1909

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input checked="" type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input checked="" type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	---	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: _____ Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.

Corpus Christi Roman Catholic Church at 161 Clark Street and church complex occupy the northern half of the block bound Kent Street to the north, Paderewski Drive to the south, Clark Street to the west, and Sears to the east. The church fronts Clark Street and extends east to Sears Street. The church is flanked by a Convent (179 Clark St.) and a Rectory (199 Clark St.). A ten-ft. sandstone block wall extends along the northern and eastern perimeter of the church complex. Other church buildings include the Copus Christi School, located on the opposite side of the street at 174 Clark Street and the Parish Clubhouse (165 Sears Street). (See individual forms) Clark Street is a five-block long residential street between Broadway and Memorial Drive. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal stands a couple of blocks to the southeast.

A twin-towered, Romanesque style church constructed of rusticated red Medina sandstone. It has a rectangular plan that measures 90-ft wide and 175-ft-deep. The imposing square towers rise to a height of 175-ft, the nave stands at a height of 90-ft, and the side aisles are 40-ft high. Heavy, coursed quarry-faced ashlar masonry distinguishes the ground floor from the random, quarry faced masonry of the upper portion of the church. The west façade has round-arched portals in the nave and towers. Each portal features double-leaf paneled doors and a tympanum with stained glass. The nave portal features a foliated compound arch in the door surround, Romanesque capitals, and a quatrefoil in the tympanum. A blind arcade accents the ground floor and gable. The façade features a rose window with a center quatrefoil and stone tracery. A triple window grouping of small round-arched windows punctuates the gable end. The upper zones of the square towers feature a clock in each elevation. The octagonal-shaped belfries have coursed dressed ashlar masonry, louvered openings, and copper sheathed cupolas punctuated by an oculus in each side.


The ten large nave windows were executed by Franz Mayer of Munich, Germany. The interior includes an apse with a depiction of Raphael's *Disputa* in the semidome. The capitals and nave columns were carved by J. Shepperd Craig, a Scottish immigrant who settled in Buffalo in the early twentieth century. The interior was fitted 11,000 lights. The church is equipped with its own generator system, which illuminated a combination of chandeliers, a fully lighted sanctuary arch and lighted nave arcades.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The Corpus Christi Roman Catholic Church at 161 Clark Street is an excellent example of a Romanesque style church constructed in the first decade of the twentieth century in the Broadway-Fillmore Avenue. This congregation was founded in 1898 by Franciscan Friars to minister to the needs of the rapidly growing Polish community. Designed by the local firm Schmill & Gould, the Medina sandstone church was dedicated in 1909. The building's most notable exterior feature is the pair of landmark towers that rise cliff-like above the street, and dominate the neighborhood. The exceptional interior features significant ecclesiastical artwork, such as murals and stained glass windows imported from Germany, all of which is illuminated by 11,000 electric light bulbs arrayed throughout the nave. The dwindling congregation recently received a reprieve from the diocese's order to close the giant edifice. In 1929, the New York Central Railroad had purchased and demolished nearly 300 homes in the immediate area, which resulted in a loss of roughly 250 families for the congregation. The Father Justin Rosary Hour began here in 1931. It is a Catholic Catechetical radio program in Polish that is the oldest continuous hour-long religious network program in the Polish language in the world. The program is still broadcast from the network of 40 Radio Stations across United States and Canada.

Corpus Christi continues to offer-Polish language masses, despite the dwindling parish membership. The Franciscans transferred the parish to the Pauline Fathers in early 2004.

MAP: Sanborn Map (Revised 1986) – Plate 199



PHOTOGRAPH: (Broadway-Fillmore R-2; N-11, 12, 22)







HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) St. Kolbe Center Ladies Club

Address or Street Location 174-176 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Religious Education Current use Religious Social

Architect/Builder, if known Carl Schmill & Son Date of construction, if known 1928

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input checked="" type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input checked="" type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq. , Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


St. Kolbe Center Ladies Club is located at **174-176 Clark Street** on the west side of the street, opposite the Corpus Christi church complex, between Paderewski and Kent streets. Clark Street is a five-block long residential street between Broadway and Memorial Drive. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal stands a couple of blocks to the southeast.

A two-story, brick, Neo-Classical inspired building. The façade has an elaborate entry bay with stone voussoirs, stone accent tabs and an inscribed stone tympanum. It has symmetrical fenestration with the lower façade windows retaining their original six-over-six double-hung wood sash. The upper façade window openings are set in an arcade and feature a heavy, continuous stone sill and stone accents. A series of rosettes are located above. A stone cornice accents the roofline.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

St. Kolbe Center Ladies Club at **174-176 Clark Street** is significant as an excellent example of an ancillary religious building constructed in the Neoclassical style in the early twentieth century. Designed by Carl Schmill & Son, it was one of two buildings constructed by congregation at that time. It was built as an additional parochial school to supplement the original school building (1898, Carl Schmill) across the street, now demolished. It was later used as a ladies club for the parish.

MAP: Sanborn Map (Revised 1986) – Plate 196



PHOTOGRAPH: (Broadway-Fillmore R-9; N-34)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) Corpus Christi Convent

Address or Street Location 179 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Religious Current use Religious

Architect/Builder, if known Schmill & Gould Date of construction, if known 1906

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input checked="" type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input checked="" type="checkbox"/> slate
Foundation:	<input checked="" type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


Corpus Christi Convent at 179 Clark Street is located on the east side of the street, between Paderewski and Kent streets. Clark Street is a five-block long residential street between Broadway and Memorial Drive. It is part of the Corpus Christi Roman Catholic Church complex. The vacant lot to the south marks the site of the former Corpus Christi School. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal stands a couple of blocks to the southeast.

A three-and-one-half story, brick masonry building with a Mansard roof. The main section is a rectangular block that is nine-bays-wide and three-bays-deep and is set on a raised, limestone foundation. The west façade and south elevation have full-height, projecting bays with pediment. The original main entrance has been altered by the addition of a vestibule. Fenestration is symmetrical with one-over-one double-hung sash, and sandstone sills and lintels. The roofline is accented by a cornice with dentil course. A two-story, brick masonry Chapel is attached to the east elevation of the convent. The first floor has tall narrow, round-arched window openings with stained glass.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

Corpus Christi Convent at 179 Clark Street is significant as an excellent example an ancillary religious building constructed in the first decade of the twentieth century. It was designed by the local firm of Schmill & Gould, who also designed Corpus Christi Church. With its mansard roof and projecting gables, the convent is similar in design to Carl Schmill's earlier church rectory (1900).

MAP: Sanborn Map (Revised 1986) – Plate 199



PHOTOGRAPH: (Broadway-Fillmore R-15; N-32)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 180 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known ca.1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The multiple-family house at **180 Clark Street** is located on the west side of the street, opposite the Corpus Christi church complex, between Paderewski and Kent streets. Clark Street is a five-block long residential street between Broadway and Memorial Drive. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal is located a few blocks to the southeast.

A one-and-one half-story, frame, front-gabled extended workers' cottage with no foundation. It has a rectangular plan and no basement. The façade has Craftsman-detailed full-width porch with a brick foundation and pedestals, battered, square, paneled supports and a wood-shingled pediment. The main entrance with sidelights is located in the north bay. Exterior wall fabrics are clapboard and wood shingle. Fenestration is casement and one-over-one, double-hung wood sash. Eastlake molding accents the gable end. Extending west from the west end of the main block are two one-story, gabled-roof additions with entries and gabled dormers on the south elevation. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 180 Clark Street is significant as a good representative example of a late nineteenth century, extended workers' cottage with an early twentieth century Craftsman porch. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 196



PHOTOGRAPH: (Broadway-Fillmore R-11; N-9)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY USN: _____

IDENTIFICATION

Property name (if any) Urban Funeral Home

Address or Street Location 188 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Vacant

Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input checked="" type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows; additions ca. 1910, 1933, 1936, 1950 Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The former Urban Funeral Home at **188 Clark Street** is located on the west side of the street, opposite the Corpus Christi church complex, between Paderewski and Kent streets. Clark Street is a five-block long residential street between Broadway and Memorial Drive. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal is located a few blocks to the southeast.

Originally constructed as a single-family residence, the current building is a heavily modified, two-and-one-half story building with a unified first floor commercial front. The façade incorporates architectural details of the Colonial Revival, Neo-Classical and Craftsman styles. The façade of the main block (southern section) is faced with brick. It has a shallow portico supported by four Corinthian-like columns. The main entrance bay and window openings have Colonial Revival broken pediments. The second floor has two, gabled, projecting bays with sunburst patterns. The roofline is further distinguished by a clipped gable. The modern, one-story, brick addition extends from the north elevation of the main block.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 188 Clark Street is significant as a good representative example of a late nineteenth century single-family residence converted into a commercial building with a combination of architectural styles that include Colonial Revival, Neo-Classical and Craftsman styles. The frame house was enlarged for Casimer Urban's funeral home in the 1930's; in 1950, a brick and concrete chapel was added to the north. The Urban Funeral Home is now vacant.

MAP: Sanborn Map (Revised 1986) – Plate 196



PHOTOGRAPH: (Broadway-Fillmore R-11; N-8)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) Corpus Christi Rectory

Address or Street Location 199 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Religious Current use Religious

Architect/Builder, if known Carl Schmill Date of construction, if known 1900

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input checked="" type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation: stone brick poured concrete concrete block

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


Corpus Christi Rectory at 199 Clark Street is located on the east side of the street between Paderewski and Kent streets. Clark Street is a five-block long residential street between Broadway and Memorial Drive. It is part of the Corpus Christi Roman Catholic Church complex. The vacant lot to the south marks the site of the former Corpus Christi School. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal stands a couple of blocks to the southeast.

A three-and-one-half story, brick masonry building with a Mansard roof and gabled dormers. The main section is a rectangular block that is eight-bays-wide and three-bays-deep and is set on a raised, limestone foundation. The west façade and north elevation have full-height, projecting bays with pediment. The original main entrance has been altered by the addition of a vestibule. Fenestration is symmetrical with one-over-one double-hung sash, and sandstone sills and lintels. The roofline is accented by a cornice with dentil course. The west façade pediment features statuary niche. A one-story, single-bay, brick hyphen connects the rectory with the church, which is located to the south.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

Corpus Christi Rectory at 199 Clark Street is significant as an excellent example an ancillary religious building constructed in the first decade of the twentieth century. It was designed by Carl Schmill of the local firm of Schmill & Gould, who also designed Corpus Christi Church. With its mansard roof and projecting gables, the convent is similar in design to Carl Schmill's earlier church rectory (1900).

MAP: Sanborn Map (Revised 1986) – Plate 199



PHOTOGRAPH: (Broadway-Fillmore R-15; N-31)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 214 Clark Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **214 Clark Street** is located on the west side of the street, between Kent Street and Broadway. Clark Street is a five-block long residential street between Broadway and Memorial Drive. The surrounding area is densely built-up with residences from the last decade of the nineteenth century through the first decade of the twentieth century. The former New York Central terminal stands a few blocks to the southeast.

A one-and-one-half story, front-gabled, frame, extended workers' cottage with no foundation. It has a rectangular plan and no basement. The façade has an entry door and a modern stoop located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash. Extending west north from the west end of the main block are two one-story, gabled-roof additions with side entrances. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 214 Clark Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 196



PHOTOGRAPH: (Broadway-Fillmore R-11; N-7)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION & HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 89 Colt Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation: stone brick poured concrete concrete block

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **89 Coit Street** is located on the east side of the street, between William and Peckham streets. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width Craftsman porch with battered, paneled, square columns and a hipped roof. The original rail has been replaced. The main entrance with sidelights is in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash and casement. The south slope has gabled dormer. Extending east from the east end of the main block are two one-story, gabled-roof additions with entrance porch. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at **89 Coit Street** is significant as a good representative example of a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. The original house, measuring 14x18 feet, was repaired in 1888 by Henry Heintze, and has since been altered and enlarged. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 209



PHOTOGRAPH: (Broadway-Fillmore R-9; N-21)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 113 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq. , Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **113 Coit Street** is located is located on the east side of the street, between William and Peckham streets. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width porch with Craftsman-detail that includes a rusticated concrete block foundation, battered, paneled, square piers, solid rail and wood-shingled pediment. The main entrance is located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash and casement. The south slope has gabled dormer. Extending east from the east end of the main block are two one-story, gabled-roof additions with entrance porch. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 113 Coit Street is significant as a good representative example of a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. The house received an addition in 1929 and its current porch in 1933. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 209



PHOTOGRAPH: (Broadway-Fillmore R-9; N-20)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 119 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: single-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **119 Coit Street** is located on the east side of the street, between William and Peckham streets. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width porch with replacement supports and rail, and its original wood-shingled pediment. The main entrance is located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash and casement. The south slope has gabled dormer. Extending east from the east end of the main block are two one-story, gabled-roof additions with entrance porch. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 119 Coit Street is significant as a good representative example of a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. The house received a kitchen addition in the rear for Joseph Michaels in 1885. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1886) – Plate 209



PHOTOGRAPH: (Broadway-Fillmore R-9; N-19)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 123 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq. , Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **123 Coit Street** is located on the east side of the street, between William and Peckham streets. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width porch with replacement supports and rail, and its original wood-shingled pediment. The main entrance is located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash and casement. The south slope has gabled dormer. Extending east from the east end of the main block are two one-story, gabled-roof additions with entrance porch. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 123 Coit Street is significant as a good representative example of a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 209



PHOTOGRAPH: (Broadway-Fillmore R-9; N-18)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 125 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **125 Coit Street** is located on the east side of the street, between William and Peckham streets. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood.

A one-and-one-half story, frame workers' cottage with a steeply-pitched, front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width porch with replacement supports and rail, and its original wood-shingled pediment. The main entrance is located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash and casement. The south slope has a gabled dormer. Extending east from the east end of the main block are two one-story, gabled-roof additions with entrance porch. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 125 Coit Street is significant as a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 209



PHOTOGRAPH: (Broadway-Fillmore R-9; N-16)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 128 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input checked="" type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **128 Coit Street** is located on the west side of the street, between William and Peckham streets. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood. A vacant lot borders the property to the north.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width porch with wood shingled-foundation, a bowed solid rail, Tuscan Doric-type columns, and a pediment above the entry. The main entrance is located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash and casement. The south slope has gabled dormer. Extending west from the west end of the main block are two one-story, gabled-roof additions with entrance porch. A brick chimney rests on the center ridge of the main block and rear additions.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 128 Coit Street is significant as a good representative example of a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 209



PHOTOGRAPH: (Broadway-Fillmore R-9; N-17)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 135 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: single-family Current use Vacant

Architect/Builder, if known _____ Date of construction, if known ca.1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **135 Coit Street** is located on the east side of the street, between William and Peckham streets. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood. A vacant lot borders the property to the north.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width Craftsman-detailed porch with battered, square wooden columns, an open wooden rail, and a gabled roof with exposed rafter tail ends and brackets. The main entrance is located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash and casement. Extending east from the east end of the main block are two one-story, gabled-roof additions. A brick chimney rests on the center ridge of the rear addition. A single-bay, hipped roof garage sheathed with clapboard stands at the rear of the lot.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 135 Coit Street is significant as a good representative example of a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 209



PHOTOGRAPH: (Broadway-Fillmore R-9; N-15)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 140 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: single-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The building 140 Coit Street is located on the west side of the street, between William and Peckham streets. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood. Vacant lots border the property to the north and south.

A one-and-one-half story, frame, workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width Craftsman-detailed porch with battered, square piers set on square, paneled pedestals, an open wooden rail, and a wood-shingled gabled roof with cornice returns. The main entrance is located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash. Extending west from the west end of the main block is a one-story, gabled-roof addition with entry on the south elevation.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 140 Coit Street is significant as a good representative example of a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 209



PHOTOGRAPH: (Broadway-Fillmore R-9; N-14)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 209 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **209 Coit Street** is located on the east side of the street, between Peckham and Paderewski streets. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood. A vacant lot borders the property to the south.

A one-and-one-half story, frame, workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width porch with replacement rail and supports, and a hipped roof. The main entrance is located in the north bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash. Extending east from the east end of the main block is a one-story, gabled-roof addition with entry on the south elevation. Two brick chimneys rest on the ridge of the main block.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 209 Coit Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 203



PHOTOGRAPH: (Broadway-Fillmore R-9; N-13)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 240 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: single-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1920

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input checked="" type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **240 Coit Street** is located on the west side of the street, between and Paderewski Street and Broadway. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood. A vacant lot borders the property to the south.

A one-and-one-half story, frame, Craftsman workers' cottage with a hipped roof. It has a rectangular plan and is set on a rusticated concrete block foundation. The façade has a full-width Craftsman porch with a rusticated concrete block foundation, battered, square piers, an open wooden rail and a hipped roof. The main entrance is located in the north bay. Exterior wall fabric is clapboard on the first floor and wood shingle on the upper story. Fenestration is one-over-one, double-hung wood sash. A hipped-dormer is located on the east slope and a shed dormer rest on the south slope. A brick chimney rests on the center ridge. A three-bay garage of brick and concrete block construction stands at the rear of the lot.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 240 Coit Street is significant is an excellent example of a Craftsman workers' cottage constructed in the 1920s in the Broadway-Fillmore neighborhood. This house was enlarged for Mary Dudziak in 1935, and she added the concrete block garage in 1939. Unlike the typical extended workers' cottages constructed in the late nineteenth century that are common in the neighborhood, this is a Craftsman style "kit" house.

MAP: Sanborn Map (Revised 1986) – Plate 194



PHOTOGRAPH: (Broadway-Fillmore R-9; N-12)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 256 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known ca. 1880

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The multiple-family house at **256 Coit Street** is located on the west side of the street, between and Paderewski Street and Broadway. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood. A vacant lot borders the property to the north.

A one-and-one-half story, frame, workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width Craftsman porch with a wood-shingled foundation, battered, square columns with brackets, a replacement metal rail and a hipped roof with pediment above the entry. The façade has a projecting entry bay and a triple window-grouping. Exterior wall fabrics are clapboard on the main block and wood shingle in the gable end. Fenestration is one-over-one, double-hung wood sash. A paired window grouping with Cottage-type sash and pent is located in the gable peak. A hipped dormer is located on the east slope and a shed dormer rest on the south slope. A brick chimney rests on the center ridge. A one-story gabled addition extends west from the west end of the main block. A carriage house stands at the rear of the lot.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 256 Coit Street is significant as a late nineteenth century, extended workers' cottage with early twentieth century Craftsman detailing. The original house was moved back and enlarged by Leo R. Mazurowski in 1915. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 194



PHOTOGRAPH: (Broadway-Fillmore R-9; N-11)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 283 Coit Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple -family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852 -2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **283 Coit Street** is located east side of the street, between and Paderewski Street and Broadway. The property is located in the southwestern corner of the Broadway-Fillmore neighborhood.

A two-story, frame, hipped-roof cottage with Craftsman detailing. It has a rectangular plan and no foundation. The façade has a full-width Craftsman porch with a rusticated concrete block foundation, battered, square, paneled piers and a replacement metal rail. The main entrance is located in the north bay. Exterior wall fabrics are clapboard on the first floor and wood shingle on the upper floor. Fenestration is one-over-one, double-hung wood sash. A hipped dormer is located on the west slope. A one-story addition with entry on the south elevation extends east from the east end of the main block. A brick chimney rests on the center ridge.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 283 Coit Street is significant as a good representative example of a two-story late nineteenth century workers' cottage with Craftsman details. A three family tenement, it was enlarged to the rear in 1904 for Piotr Tabaczynski; and was enlarged again in 1919 for Adam Barezykowski.. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 195



PHOTOGRAPH: (Broadway-Fillmore R-9; N-10)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION & HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 11 Concord Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation: stone brick poured concrete concrete block

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The multiple-family house at **11 Concord Street** is located on the south side of the street. Concord Street is a one-block long east-west street extending from Memorial Drive to Curtiss Street. The former New York Central Terminal is located two blocks to the south.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has a full-width porch with replacement supports and rail. The main entrance is in the west bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash and casement. Eastlake molding accents the gable end. The east elevation has a side entrance. Two brick chimneys rest on the roof ridge.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 11 Concord Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 200



PHOTOGRAPH: (Broadway-Fillmore R-15; N-26)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION & HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 14 Concord Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation: stone brick poured concrete concrete block

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **14 Concord Street** is located on the north side of the street. Concord Street is a one-block long east-west street extending from Memorial Drive to Curtiss Street. The former New York Central Terminal is located two blocks to the south.

A one-and-one-half story, frame workers' cottage with a front-gabled roof and cornice returns. It has a rectangular plan and no foundation. The façade has a full-width Craftsman-detailed porch with square columns, an open wooden rail and pediment above the entry. The main entrance is in the west bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash. A paired window grouping with pent is located in the gable end. Two one-story additions extend north from the north end of the main block. Two brick chimneys rest on the roof ridge.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 14 Concord Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. The original rear section received a front addition in 1910 for J. Witkowski. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 198



PHOTOGRAPH: (Broadway-Fillmore R-15; N-11)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION & HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 28 Concord Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation: stone brick poured concrete concrete block

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The multiple-family house at **28 Concord Street** is located on the north side of the street. Concord Street is a one-block long east-west street extending from Memorial Drive to Curtiss Street. The former New York Central Terminal is located two blocks to the south.

A one-and-one-half story, frame workers' cottage with a front-gabled roof and cornice returns. It has a rectangular plan and no foundation. The façade has an entry with a bracketed hood and a replacement stoop in the west bay. Exterior wall fabric is clapboard. Fenestration is one-over-one, double-hung wood sash. A single window opening punctuates the gable peak. A one-story addition with entrance on the east elevation extends north from the north end of the main block. A brick chimney rests on the roof ridge of the main block and the rear addition. A single-bay garage stands at the rear of the lot.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 28 Concord Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 198



PHOTOGRAPH: (Broadway-Fillmore R-15; N-10)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION & HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 33 Concord Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation: stone brick poured concrete concrete block

Other materials and their location: _____

Alterations, if known: Replacement windows, addition (1906) Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **33 Concord Street** is located on the south side of the street. Concord Street is a one-block long east-west street extending from Memorial Drive to Curtiss Street. The former New York Central Terminal is located two blocks to the south.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has an entry and a replacement stoop in the west bay. Exterior wall fabric is clapboard. Fenestration is three- and one-over-one, double-hung wood sash. Eastlake molding accents the gable end. A one-story addition extends south from the south from the main block. A brick chimney rests on the roof ridge of the main block. A single-bay, hipped-roof garage stands at the rear of the lot.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 33 Concord Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 200



PHOTOGRAPH: (Broadway-Fillmore R-15; N-25)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION & HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 34 Concord Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: single-family

Architect/Builder, if known _____ Date of construction, if known ca. 1890

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation: stone brick poured concrete concrete block

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The single-family house at **34 Concord Street** is located on the north side of the street. Concord Street is a one-block long east-west street extending from Memorial Drive to Curtiss Street. The former New York Central Terminal is located two blocks to the south.

A one-and-one-half story, frame workers' cottage with a front-gabled roof. It has a rectangular plan and no foundation. The façade has an entry and a replacement stoop in the west bay. Exterior wall fabric is clapboard. Fenestration is three- and one-over-one, double-hung wood sash. A one-story addition with entry on the east elevation extends north from the north from the main block. A brick chimney rests on the roof ridge of the main block and the rear addition.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 34 Concord Street is significant as a good representative example of a late nineteenth century, extended workers' cottage. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail. In 1891 a house of this sort cost \$885 to build and might rent for \$9 or \$10 per month.

MAP: Sanborn Map (Revised 1986) – Plate 198



PHOTOGRAPH: (Broadway-Fillmore R-15; N-9)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 416 Curtiss Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Residence: multiple-family

Architect/Builder, if known _____ Date of construction, if known 1925

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other	
Roof:	<input checked="" type="checkbox"/> asphalt, shingle	<input type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The two-family house at **416 Curtiss Street** is located on the northwest corner of Curtiss and Dover streets. Curtiss Street is a four-block long north-west street that extends from Broadway and terminates at the northern boundary of the former New York Central Terminal complex. The property is located in the southeastern part of the Broadway-Fillmore neighborhood.

A two-and-one-half story, front-gabled residence with Craftsman detailing. It has a full-width porch with rusticated concrete foundation and pedestals, battered square piers, an open wooden rail and a hipped roof. The entrance door is located in the north bay. Fenestration is one-over-one-double-hung wood sash. Exterior fabric on the main block is clapboard and the gable end is sheathed with wood shingle. A paired window grouping with pent punctuates the gable peak. A one-story addition with entry on the south elevation extends west from the west end of the main block.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 416 Curtiss Street is significant as a good representative example of a two-story-and-one-half story Craftsman workers' cottage constructed in the early twentieth century in the Broadway-Fillmore neighborhood. Nos. 416 and 418 Curtiss Street were built as two-family houses for Vincent Bielanski. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 198



PHOTOGRAPH: (Broadway-Fillmore R-15; N-6)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY USN: _____

IDENTIFICATION

Property name (if any) _____

Address or Street Location 418 Curtiss Street

County Erie Town/City Buffalo Village/Hamlet: _____

Owner _____ Address _____

Original use Residence: multiple-family Current use Vacant

Architect/Builder, if known _____ Date of construction, if known 1925

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input checked="" type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The building at **418 Curtiss Street** is located on the west side of the street between Dover Street and Broadway. Curtiss Street is a four-block long north-west street that extends from Broadway and terminates at the northern boundary of the former New York Central Terminal complex. The property is located in the southeastern part of the Broadway-Fillmore neighborhood. A vacant lot borders the property to the north.

A two-and-one-half story, front-gabled residence with Craftsman detailing. It has a full-width porch with rusticated concrete foundation and pedestals, battered square piers, an open wooden rail and a hipped roof. The entrance door is located in the north bay. Fenestration is one-over-one-double-hung wood sash. Exterior fabric on the main block is clapboard and the gable end is sheathed with wood shingle. The peak has a pent over a small window opening. The south elevation has a side entrance with canopy. A one-story addition extends west from the west end of the main block. It has a single-bay, hipped roof garage at the rear of the lot. The building is presently vacant; the ground floor window and door openings are boarded and the upper windows are either broken or missing.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 418 Curtiss Street is significant as a good representative example of a two-story-and-one-half story Craftsman workers' cottage constructed in the early twentieth century in the Broadway-Fillmore neighborhood. Nos. 416 and 418 Curtiss Street were built as two-family houses for Vincent Bielanski. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 198



PHOTOGRAPH: (Broadway-Fillmore R-15; N-7)





HISTORIC RESOURCE INVENTORY FORM

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

OFFICE USE ONLY
USN: _____

IDENTIFICATION

Property name (if any) _____
Address or Street Location 426 Curtiss Street
County Erie Town/City Buffalo Village/Hamlet: _____
Owner _____ Address _____
Original use Residence: multiple-family Current use Vacant
Architect/Builder, if known _____ Date of construction, if known ca. 1900

DESCRIPTION

Materials – please check those materials that are visible

Exterior Walls:	<input checked="" type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood
	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
	<input type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other

Roof: asphalt, shingle asphalt, roll wood shingle metal slate

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
-------------	--------------------------------	--------------------------------	--	---

Other materials and their location: _____

Alterations, if known: Replacement windows Date: _____

Condition: excellent good fair deteriorated

Photos

Provide several clear, original photographs of the property proposed for nomination. Submitted views should represent the property as a whole. For buildings or structures, this includes exterior and interior views, general setting, outbuildings and landscape features. Color prints are acceptable for initial submissions.

Please staple one photograph providing a complete view of the structure or property to the front of this sheet. Additional views should be submitted in a separate envelope or stapled to a continuation sheet.

Maps

Attach a printed or drawn locational map indicating the location of the property in relationship to streets, intersections or other widely recognized features so that the property can be accurately positioned. Show a north arrow. Include a scale or estimate distances where possible.

Study: City of Buffalo Intensive Level Historic Resources Survey: Broadway-Fillmore Neighborhood

Prepared by: Clinton Brown Company Architecture, pc Address: 2100 Rand Building, 14 Lafayette Sq., Buffalo NY 14203

Telephone: (716) 852-2020 ext. Email: cbca@buffnet.net Date: 03/2004

(See following pages)

PLEASE PROVIDE THE FOLLOWING INFORMATION

IF YOU ARE PREPARING A NATIONAL REGISTER NOMINATION, PLEASE REFER TO THE ATTACHED INSTRUCTONS

Narrative Description of Property: Briefly describe the property and its setting. Include a verbal description of the location (e.g., north side of NY 17, west of Jones Road); a general description of the building, structure or feature including such items as architectural style (if known), number of stories, type and shape of roof (flat, gabled, mansard, shed or other), materials and landscape features. Identify and describe any associated buildings, structures or features on the property, such as garages, silos, privies, pools, and gravesites. Identify any known exterior and interior alterations such as additions, replacement windows, aluminum or vinyl siding or changes in plan. Include dates of construction and alteration, if known. Attach additional sheets as needed.


The building at **426 Curtiss Street** is located on the west side of the street between Dover Street and Broadway. Curtiss Street is a four-block long north-west street that extends from Broadway and terminates at the northern boundary of the former New York Central Terminal complex. The property is located in the southeastern part of the Broadway-Fillmore neighborhood. A vacant lot borders the property to the south.

A two-and-one-half story, front-gabled residence with Craftsman detailing. It has a full-width porch with rusticated concrete foundation and pedestals, battered square piers, an open wooden rail and a hipped roof. The entrance door is located in the north bay. Fenestration is three-and one-over-one-double-hung wood sash. Exterior fabric is clapboard. The peak has a pent over a small window opening. The south elevation has a side entrance with canopy. A gabled dormer rests on the south slope. A one-story addition extends west from the west end of the main block.

Narrative Description of Significance: Briefly describe those characteristics by which this property may be considered historically significant. Significance may include, but is not limited to, a structure being an intact representative of an architectural or engineering type or style (e.g., Gothic Revival style cottage, Pratt through-truss bridge); association with historic events or broad patterns of local, state or national history (e.g.; a cotton mill from a period of growth in local history, a seaside cottage representing a locale's history as a resort community, a structure associated with activities of the "underground railroad."); or by association with persons or organizations significant at a local, state or national level. Simply put, why is this property important to you and the community. Attach additional sheets as needed.

The building at 426 Curtiss Street is significant as a as a good representative example of a two-story-and-one-half story Craftsman workers' cottage constructed in ca. 1900 in the Broadway-Fillmore neighborhood. The house was moved here from 1209 Broadway by Stanislaus Lipowicz in 1912, to make way for his new grocery warehouse at that site. This type of modest house quickly permeated the Broadway-Fillmore neighborhood, as it could be constructed inexpensively and quickly to accommodate the rapid influx of immigrants, largely Polish, to the Broadway-Fillmore area. Unlike the neighborhood's religious and commercial buildings, the vast majority of the housing stock in the Broadway-Fillmore area would have been erected to plans available to builders in books or by mail.

MAP: Sanborn Map (Revised 1986) – Plate 198



PHOTOGRAPH: (Broadway-Fillmore R-15; N-8)



